



NATIONAL TRANSPORTATION SAFETY BOARD

Eastern Region – Ashburn, Virginia

RECORD OF CONVERSATION

Who: Steve Berkey, Anglin Aircraft Recovery

When: June 9, 2016

RE: ERA16CA203

In a telephone conversation, Mr. Berkey stated that none of the fuel tanks had been breached. He drained about 20 oz of fuel from the right wing and about 21 gallons from the left wing.

Leah D. Read

Sr. Air Safety Investigator

National Transportation Safety Board