

<u>NATIONAL TRANSPORTATION SAFETY BOARD</u>		Time 10:00 am	Date 6/28/2016
RECORD OF: ☐ VISIT ☐ CONFERENCE ☒ TELEPHONE CALL			
Name (s) of Person (s) contacted or in conference and location		Routing	
Mr. Michael Boyer-Pilot		Symbol	Initials
Subject: N9297J-Williamsburg-Jamestown Airport (JGG)			
Digest: In a telephone discussion with Mr. Michael Boyer, he stated that he was approaching JGG he was on the approach to final when he noticed he was left of center line. He decided to do a go-around and come back for a stabilized approach. As he added power the airplane pitched up and veered to the left. He said that before he could regain control of the airplane it stalled and collided with the trees. According to the pilot there were no preimpact mechanical failures or malfunctions with the airframe or engine that would have precluded normal operation.			
Conclusions, Action Taken, or Required: This correspondence was reviewed with pilot			
Date 6/28/2016	Title ASI	Signature Alleyne	