



Federal Aviation Administration

Memorandum

Date: December 03, 2015

To: Aircraft Accident File JFK-ATCT-0144

From: Kennedy Airport Traffic Control Tower

Subject: **INFORMATION:** Partial Transcript
Aircraft Accident, N622BT
Rockaway, NY, November 05, 2015

This transcription covers the Kennedy Airport Traffic Control Tower (ATCT) LC2 LC position for the time period from November 05, 2015, 0001 UTC, to November 05, 2015, 0103 UTC.

Agencies Making Transmissions

N622BT
JFK LC2

Abbreviations

N622BT
JFK LC2

I certify that the following is a true transcription of the recorded conversations pertaining to the subject Aircraft Accident involving N622BT.

A handwritten signature in black ink, which appears to be "Salvatore Barbaro", is written over a black rectangular redaction box.

Salvatore Barbaro
Quality Control Staff Specialist
Kennedy Tower

0001
(0002-0030)

0031

0031:59 N622BT kennedy tower flight design november six two two bravo
tango one thousand four hundred for four hundred

0032

0032:06 JFK LC2 november two two bravo tango kennedy tower altimeter is
three zero three five say your request

0032:12 N622BT two bravo tango uh transition south shore under class
bravo

0032:21 JFK LC2 november two bravo tango cleared along the uh shoreline
maintain v f r at or below five hundred caution wake

JFK-ATCT-0144
N622BT

Page 2 of 2

turbulence all types overhead departing to the south

0032:30 N622BT v f r at or below five hundred caution wake turbulence two
bravo tango roger

0033
(0034-0102)
0103

End of Transcript
