

FAX TO STEVE NEWCOMER FAA ATL

FAX # [REDACTED]

Tom Lycett

01/31/2017

(N5345L)

Aircraft Make Piper	Model PA 28-180	Serial # 28-4648	N # N57WV	Date 18 AUG 2015
Type Service ANNUAL- ENG 1328 SMOH 5483.T.T.E. 1 62/80 2 75/80 3 77/80 4 74/80				Tach 320.8 321. 5115.42 T.T.
1)	Discrepancy			Technician
	Corrective Action			Time
2)	Right & Left Fuel Drain Leaking			MW
	Installed New Drain			.25
3)	ELT Batterys Need Replaced			
	Installed New Batterys Dec 2024 & Tested Per FAA 19			
4)	Aircraft Battery Need Replaced Will Not Keep Charges			MW
	Installed New Battery			.25
5)	A.D. 2013-02-13 STAB. Control System AS PER PIPER			MW
	M.S.B. # 1245A, RECURRING EACH 2,000 HRS. OR 7 YRS, WHICH EVER FIRST			-1.5
6)				
7)				
8)	Need New ENG Log Book			
9)				
10)				
11)				
12)	Top 30 Lower 35 40+-5			Up 16° ± 1° Down 2° ± 1°

OVER FOR PARTS LIST

[illegible]