

Operations
Number of
entries.)

Name

HALIL

22

YEAR 20 14 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
Apr 20	8.3	8.3		ANNUAL Conditional Inspection Completed I certify that this aircraft N380JA has been inspected on this date of Apr. 20, 2014 in accordance with Detail of Appendix D, part 43 and found to be in condition for safe operation [REDACTED] owner - Repairman Certificate [REDACTED]
Apr 20 2014	22.9	22.9		Landing Incident causing right wing lower damage to tip, right gear leg damaged, wings removed Engine removed and Prop for repair.

YEAR 20 16 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries)
Jan 2	229		229	Airframe repairs complete Right lower wing tip repaired recovered. Tail wheel assembly replaced with Maule unit. New spring attach bar on rudder. Right Landing Gear Leg Made from scratch. Completely new Entire fuselage repainted, as right wing and tail parts. New bungee springs installed on both gear legs New rebuilt Horizon tachometer installed from Horizon factory. Propellor and prop governor rebuilt with yellow tag foam Sensenich Prop, Gainsville Gc. Prop Hub replaced.

YEAR 20 16 DATE	RECORDING TACH TIME
	2

Number of
specific entries.)

YEAR 2016
DATE

RECORDING
TACH
TIME

TODAY'S FLIGHT

TOTAL
TIME IN
SERVICE

Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

22.9

22,9

Engine Continental 70360 repair
included the following
Crankshaft Magnaflux mains reground
Connecting rods Magnaflux - .010
Camsshaft reground to new specs A.E.A. inc.
Lifters reground A.E.A. Co. Inc.
Gears on Crank & cam replaced A.E.A. inc.
Starter Adapter rebuilt. A.E.A. inc.
New Piston rings, ALL NEW Bearings
New rod-con. bolts. NEW SEALS &
Gaskets through out. Previously Cylinder
INTAKE & Exhaust VALVES reground. replaced.

YEAR 20 <u>16</u> DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
Apr. 10	22.9		22.9	Annual Condition Inspection Completed I certify that this aircraft N380JA has been inspected on this date of April 10, 2016, in accordance with Detail of Appendix, part 43 and found to be in condition for SAFE operation. [REDACTED] Bruce Ryskamp Repairman Certificate [REDACTED] April 10 - 2016
Apr. 10	24.7	1.9	24.7	First Flight OK. After rebuild