

Prepared by


NATIONAL TRANSPORTATION SAFETY BOARD
Office of Aviation Safety
Air Traffic Control Investigations

NTSB Investigation Number
ERA16FA238

**Figure 1 - N1075F - Flight Track Information
(FLL ASR-9)**

B. SOPER

JULY, 2016



Prepared by


NATIONAL TRANSPORTATION SAFETY BOARD
Office of Aviation Safety
Air Traffic Control Investigations

NTSB Investigation Number
ERA16FA238

Figure 2 - N1075F - Flight Track Information
(FLL ASR-9)

B. SOPER

JULY, 2016



Prepared by


NATIONAL TRANSPORTATION SAFETY BOARD
Office of Aviation Safety
Air Traffic Control Investigations

NTSB Investigation Number
ERA16FA238

**Figure 3 - N1075F - Flight Track Information
(MIA ASR-9)**

JULY, 2016

B. SOPER



N1075F Accident Location
26.264444 N Latitude
-80.415556 W Longitude

Prepared by


NATIONAL TRANSPORTATION SAFETY BOARD
Office of Aviation Safety
Air Traffic Control Investigations

NTSB Investigation Number
ERA16FA238


Figure 4 - N1075F - Flight Track Information
(MIA ASR-9)

B. SOPER

JULY, 2016



JULY, 2016



Prepared by

NATIONAL TRANSPORTATION SAFETY BOARD
Office of Aviation Safety
Air Traffic Control Investigations

NTSB Investigation Number
ERA16FA238

**Figure 6 - N1075F - Flight Track Information
(QMA ARSR-4)**

B. SOPER

JULY, 2016

