

, Repairs and Alterations
 ing and Certificate Number of
 ages for other specific entries)

s, LLC

1.0 Total Time 3325.8

-74/80 3-74/80 4-75/80

1 filter. Opened filter

. Installed CH48110-1

-50 Phillips oil. C-

- Checked magneto to

1, no defects noted. F.

s. H- Dressed out nicks

Paint blade faces flat

to 2005-02

has been inspected in

was determined to be in

Marlboro Aircraft

YEAR

DATE

4/17/05

RECORDING
 TACH
 TIME

1186.0

TODAY'S
 FLIGHT

TOTAL
 TIME IN
 SERVICE

3381.8

Description of Inspections, Tests, Repairs and Alterations

Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

Marlboro Aircraft Services, LLC

Farmingdale, NJ 07727

Date 6/17/05 Reg. # N-43249 Tech. Time 1186.0 Total Time 3381.8

1- Changed engine oil and filter. Opened filter and inspected for contaminants, none found. Installed CH48110-1 oil filter. Filled engine sump with 12 qts. 20w-50 Phillips oil. Run-up engine operation normal no oil leaks noted.

Aircraft returned to service.

Certificate #

Signed

Marlboro Aircraft Services, LLC

Farmingdale, NJ 07727

Date 8/24/2005 Reg. # N-43249 Tech. Time 1238.1 Total Time 3433.9

Changed engine oil and filter. Opened filter and inspected for contaminants, none found. Installed CH48110-1 oil filter. Filled engine sump with 12 qts. 20w-50 Phillips oil. Ground run engine operation normal, no oil leaks noted.

Aircraft returned to service.

Certificate #

Signed

YEAR DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
5/11/08	1306.5		3785.3	Marlboro Aircraft Services, LLC
5/11/2006	1306.5		3502.3	Reg.# N-43249 Tach Time 1306.5 Total Time 3502.3
TSMO	1178.1			Performed annual inspection IAW Piper Service Manual, FAA-FAR 43 APP D. Compression test results: Cyl. 1-74/80 2-70/80 3-75/80 4-76/80 5-75/80 6-75/80. Changed engine oil and filter. Opened filter and examined for contaminants; none found. Installed CH48110 oil filter. Filled engine sump with 12 quarts of 20w50 Phillips XC engine oil. Cleaned fuel screens. Checked magneto timing. Cleaned, gaped and rotated all spark plugs. Inspected exhaust system; no defects noted. Washed engine and cowling. lubed all hinges and engine controls.
				Aircraft returned to service. All AD's in compliance see AD compliance report
				I certify that on this date 5/11/2006 this engine and propeller have been inspected in accordance with an annual inspection and was determined to be in airworthy condition. Details on file at Marlboro Aircraft Services, LLC on work order #1594.
				Signed [Signature] William T. Bienes

YEAR DATE	RECORDING TACH TIME	TODAY'S FLIGHT	
5/11/2006	1370.0		36
12/4/07	1471.1		361

Speller have been
d was determined to
craft Services, LLC

4/24/07

YEAR DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
6/5/07	1484.0		3679.8	Marlboro Aircraft Services, LLC 1717 Highway 34 Farmingdale, NJ 07727 Reg.# N-43249 Tach Time 1484.0 Total Time 3679.8 Performed annual inspection IAW Piper Service Manual, FAA-FAR 43 APP D. Compression test results: Cyl. 1-78/80 2-76/80 3-76/80 4-77/80. Changed engine oil and filter. Opened filter and examined for contaminants; none found. Cleaned fuel screens. Checked magneto timing. Cleaned, gaped and rotated all spark plugs. Inspected exhaust system; no defects noted. Washed engine and cowling, lubed all hinges and engine controls. Aircraft returned to service. All AD's in compliance see AD compliance report I certify that on this date 6/5/2007 this engine and propeller have been inspected in accordance with an annual inspection and was determined to be in airworthy condition. Details on file at Marlboro Aircraft Services, LLC on work order # 1914. AP IA Signed William T. Bienes
TSMO	1355.6			

1, Repairs and Alterations
ing and Certificate Number of
anges for other specific entries.

is, LLC
rt Bldg. 4
lo, NJ 07727

4.0 Total Time 3679.8

annual, FAA-FAR 43 APP
3-76/80 4-77/80. Changed
or contaminants; none
iming. Cleaned, gaped and
; no defects noted.
engine controls.

o see AD compliance report

propeller have been
n and was determined to
o Aircraft Services, LLC

RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
7/10/07 1520.4		3716.2	Marlboro Aircraft Services, LLC Date 9/10/2007 Farmingdale, NJ 07727 Reg.# N-43249 Tach. Time 1520.4 Total Time 3716.2 Changed engine oil and filter. Opened filter and examined for contaminants; none found. Installed CH48110 oil filter. Filled engine sump with 10 quarts of 20w-50 Phillips X/C engine oil. Ground run engine, no leaks noted, operation normal. The aircraft, aircraft engine, propeller, or appliance identified above was repaired and inspected in accordance with current instructions in the approved maintenance manual and Regulations of the Federal Aviation Agency and is approved for return to service. Pertinent details of the repair are on file at Marlboro Aircraft Services, LLC on Work Order #1860 Certificate # [REDACTED] AP Signed [REDACTED] William T. Bienes
8/11/08 1589.7		3785.5	Marlboro Aircraft Services, LLC Date 5/29/2008 Farmingdale, NJ 07727 Reg.# N-43249 Tach. Time 1589.7 Total Time 3785.5 Changed engine oil and filter. Opened filter and examined for contaminants; none found. Installed CH48110 oil filter. Filled engine sump with 10 quarts of 20w-50 Phillips X/C engine oil. Ground run engine; no leaks noted. Operations check normal. The aircraft, aircraft engine, propeller, or appliance identified above was repaired and inspected in accordance with current instructions in the approved maintenance manual and Regulations of the Federal Aviation Agency and is approved for return to service. Pertinent details of the repair are on file at Marlboro Aircraft Services, LLC on Work Order #1958 Certificate # [REDACTED] AP Signed [REDACTED] William T. Bienes

llor have been
was determined to
aft Services, LLC

RECORDING YACHT TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
1672.8		3868.6	██████████ Date 11/6/2008 Farminedale, NJ 07727 Reg.# N-43249 Tech. Time 1672.8 Total Time 2052.8 Changed engine oil and filter. Opened filter and examined for contaminants; none found. Installed CH48110 oil filter. Filled engine sump with 10 quarts of 20W50 Phillips XC engine oil. The aircraft, aircraft engine, propeller, or appliance identified above was repaired and inspected in accordance with current instructions in the approved maintenance manual and approved for return to service by Pertinor Certific WARNING - When installing drive gear or driver onto magneto, torque nut provided to 120 to 320 inch lbs. - Use only the installation hardware provided. - Secure nut with appropriate cotter pin. Reg.# Rem left p The air current approve Pertinor Certific FAA-PMA Approved This magneto was manufactured from all new components in accordance with 14 CFR Part 21.303h and is airworthy. This magneto is FAA-PMA approved for applications listed in Unison Industries' L-1318 Document in the F-1100 Master Service Manual. For LASAL Magnetos, see L-1500 Manual. Enter magneto model, serial number, and date of installation, and attach this tag to engine logbook Magneto Model No. 6355 Magneto Serial No. 08120774 Date of Installation 4/8/2009 L-1543-A
1544.4			

C

[illegible]

YEAR DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
7/19/2009	1727.3		3923.1	Mariboro Aircraft Services, LLC Farmingdale, NJ 07727 Date 7/13/2009 Reg.# N-43249 Tach. Time 1727.3 Total Time 3923.1 Changed engine oil and filter. Opened filter and examined for contaminants; none found. Installed CH48110 oil filter. Filled engine sump with 10 quarts of 20w50 Phillips XC engine oil. The aircraft, aircraft engine, propeller, or appliance identified above was repaired and inspected in accordance with current instructions in the approved maintenance manual and Regulations of the Federal Aviation Agency and is approved for return to service. Pertinent details of the repair are on file at Mariboro Aircraft Services, LLC on Work Order #2095 Certificate # [redacted] Signed [redacted] William T. Bienes
				Mariboro Aircraft Services, LLC Date 9/1/2009 Reg.# N-43249 Tach. Time 1757.1 Total Time 3952.9 Changed engine oil and filter. Opened filter and examined for contaminants; none found. Installed CH48110 oil filter. Filled engine sump with 10 quarts of 20w50 Phillips XC engine oil. The aircraft, aircraft engine, propeller, or appliance identified above was repaired and inspected in accordance with current instructions in the approved maintenance manual and Regulations of the Federal Aviation Agency and is approved for return to service. Pertinent details of the repair are on file at Mariboro Aircraft Services, LLC on Work Order #2124 Certificate # [redacted] AP Signed [redacted] William T. Bienes

Repairs and Alterations
 and Certificate Number of
 for other specific entries

LC Date 7/13/2009

Total Time 3923.1

contaminants; none found. Installed
 50 Phillips XC engine oil.

repaired and inspected in accordance with
 of the Federal Aviation Agency and is

on Work Order #2095

William T. Bienes

HC Date 8/1/2009

Total Time 3952.9

contaminants; none found. Installed
 50 Phillips XC engine oil.

repaired and inspected in accordance with
 of the Federal Aviation Agency and is

on Work Order #2124

William T. Bienes

ROUNDING
 TACH
 TIME

TODAY'S
 FLIGHT

TOTAL
 TIME IN
 SERVICE

Description of Inspections, Tests, Repairs and Alterations

Entries must be endorsed with Name, Rating and Certificate Number of
 Technician or Repair Facility. (See back pages for other specific entries.)

Marlboro Aircraft Services, LLC

1717 Highway 34 Farmingdale, NJ 07727

Reg.# N-43249 Tach Time 1767.6 Total Time 3963.4

Performed Annual Inspection IAW Piper Service Manual, FAA-FAR APP 43
 D. Compression test results: Cyl 1-73/80 2-74/80 3-75/80 4-78/80 5-79/80
 6-77/80. Checked magneto timing. Washed engine and cowling, lubed all
 hinges and controls. Cleaned, gaped and rotated all spark plugs.

All AD's complete through 2009-10A

I certify that on this date 10/28/2009 this engine and propeller have been
 inspected in accordance with an annual inspection and was determined to be
 in airworthy condition. Details on file at Marlboro Aircraft Services, LLC on
 work order #2136.

AP IA

Signed

William T. Bienes

YEAR DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	RECORDING TACH TIME	TODAY'S FLIGHT
8/30/2010	1811.6		4007.0	██████████ ██████████ Date 8/30/2010 Farmingdale, NJ 07727 Reg.# N-43249 Tach. Time 1811.6 Total Time 4007.0 Changed engine oil and filter. Opened filter and examined for contaminants; none found. Installed CH48110 oil filter. Filled engine sump with 8 quarts of 20/50 Phillips XC engine oil. The aircraft, aircraft engine, propeller, or appliance identified above was repaired and inspected in accordance with current instructions in the approved maintenance manual and Regulations of the Federal Aviation Agency and is approved for return to service. Pertinent details of the repair are on file at Marlboro Aircraft Services, LLC on Work Order # 2231 Certificate ██████████ AP Signed ██████████ William T. Barnes	1818.5	
Tsmo	1690.1				1690	16970

s, Tests, Repairs and Alterations
Name, Rating and Certificate Number of
(See back pages for other specific entries)

Aircraft Services, LLC Date 8/30/2010

Waydole, NJ 07727

1811.6 Total Time 4007.0

and examined for contaminants; none found. Installed
parts of 20/50 Phillips XC engine oil.

and inspected in accordance with
and Regulations of the Federal Aviation Agency and is

Aircraft Services, LLC on Work Order # 2231

Signed

RECORDING
TACH
TIME

TODAY'S
FLIGHT

TOTAL
TIME IN
SERVICE

Description of Inspections, Tests, Repairs and Alterations

Entries must be endorsed with Name, Rating and Certificate Number of
Technician or Repair Facility. (See back pages for other specific entries.)

1818.5

4014.3

Marlboro Aircraft Services, LLC

Reg.# N-43249 Tach Time 1818.5 Total Time 4014.3

Performed annual inspection IAW Piper Service Manual, FAA-FAR APP 43
D. Compression test results: Cyl. 1 - 45/80 2-67/80 3-70/80 4-72/80 5-76/80
6-70/80. Removed cyl. #1 due to low compression, reinstalled cyl. #1 after
overhaul. Oil and filter changed @ 1811.6 Hrs. Filter inspected for
contaminants, none found. Cleaned fuel screen. Checked magneto timing.
Installed BA-3 air filter element. Washed engine & cowling, lubed all engine
controls. Inspected exhaust system, no defects noted. Cleaned, gaped &
rotated all spark plugs. Removed & reinstalled propeller after overhaul by
Sensenich Propeller.

I certify that on this date 12/05/2010 this engine and propeller have been
inspected in accordance with an annual inspection and were determined to
be in airworthy condition. Details on file at Marlboro Aircraft Services, LLC
on work order # 2249.

AP IA Signed

William T. Bienes

YEAR DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
				Marlboro Aircraft Services, LLC Date 06/09/2011 Farmingdale, NJ 07727 Reg.# N-43249 Tach. Time 1867.2 Total Time 4063 Changed engine oil and filter. Opened filter and inspected for contaminants: none found. Installed CH48110 oil filter and serviced sumo with 10qts of 20W50 Phillips XC engine oil. The aircraft, aircraft engine, propeller, or appliance identified above was repaired and inspected in accordance with current instructions in the approved maintenance manual and Regulations of the Federal Aviation Agency and is approved for return to service. Pertinent details of the repair are on file at Marlboro Aircraft Services, LLC on Work Order # 2296 Certificate # [redacted] AP Signed [redacted] William T. Bienes
				Marlboro Aircraft Services, LLC Date 01/19/2011 Farmingdale, NJ 07727 Reg.# N-43249 Tach. Time 1827.5 Total Time 4023.3 Starter drive gear broken and teeth missing from ring gear. Removed propeller and flywheel assy. Removed ring gear from flywheel. Installed new ring gear and reinstalled prop and flywheel. Removed starter, disassemble, reassemble starter with serviceable starter drive. The aircraft, aircraft engine, propeller, or appliance identified above was repaired and inspected in accordance with current instructions in the approved maintenance manual and Regulations of the Federal Aviation Agency and is approved for return to service. Pertinent details of the repair are on file at Marlboro Aircraft Services, LLC on Work Order # 2269 Certificate # [redacted] AP Signed [redacted] William T. Bienes

YEAR DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Donor Engine Type
6/9/11	1922.1		4117.9	(7.52)1 Reg # N 4 CH48110 oil f
1/19/11	1942.3		4138.1	(7.52)1 Reg # N Engine and oil Engine and oil

Inspections, Tests, Repairs and Alterations
 Endorsed with Name, Rating and Certificate Number of
 Facility. (See back pages for other specific entries.)

Marlboro Aircraft Services, LLC Date 06/09/2011

Tach. Time 1867.2 Total Time 4063

Oil filter and inspected for contaminants: none found. Installed
 10qts of 20W50 Phillips XC engine oil.

The aircraft, aircraft engine, propeller, or appliance identified above was repaired and inspected in accordance with
 maintenance manual and Regulations of the Federal Aviation Agency and is

at Marlboro Aircraft Services, LLC on Work Order # 2296

Signed

Date 01/19/2011

Tach. Time 1827.5 Total Time 4023.3

Propeller missing from ring gear. Removed propeller and flywheel assy.
 Installed new ring gear and reinstalled prop and flywheel. Removed
 starter with serviceable starter drive.

The aircraft, aircraft engine, propeller, or appliance identified above was repaired and inspected in accordance with
 maintenance manual and Regulations of the Federal Aviation Agency and is

at Marlboro Aircraft Services, LLC on Work Order # 2269

Signed

William T. Bienes

RECORDING
TACH
TIME

TODAY'S
FLIGHT

TOTAL
TIME IN
SERVICE

Description of Inspections, Tests, Repairs and Alterations
 Entries must be endorsed with Name, Rating and Certificate Number of
 Technician or Repair Facility. (See back pages for other specific entries.)

Marlboro Aircraft Services, LLC Date 09/13/2011

Reg.# N-43249 Tach. Time 1922.1 Total Time 4117.9

Changed engine oil and filter. Opened filter and checked for contaminants: none found. Installed
 CH48110 oil filter and serviced sump with 10qts of 20W50 Phillips XC engine oil.

The aircraft, aircraft engine, propeller, or appliance identified above was repaired and inspected in accordance with
 current instructions in the approved maintenance manual and Regulations of the Federal Aviation Agency and is
 approved for return to service.

Pertinent details of the repair are on file at Marlboro Aircraft Services, LLC on Work Order # 2324

Certificate # [redacted] AP

Signed

Marlboro Aircraft Services, LLC Date 11/15/2011

Reg.# N-43249 Tach. Time 1942.3 Total Time 4138.1

Replaced starter (PN 149NL). Cleaned lower spark plugs. Checked magneto timing, reset left magneto.
 Replaced oil sump drain.

The aircraft, aircraft engine, propeller, or appliance identified above was repaired and inspected in accordance with
 current instructions in the approved maintenance manual and Regulations of the Federal Aviation Agency and is
 approved for return to service.

Pertinent details of the repair are on file at Marlboro Aircraft Services, LLC on Work Order # 2336

Certificate # [redacted] AP

Signed

Date 12/20/2011

Farmingdale, NJ 07727

[illegible]

Reg.#	N-43249	Tach. Time	1965.2	Total Time	4161
Remove and replace spark plugs with Champion Spark plugs REM38E. Cleaned primer nozzles. Checked magneto timing. Tested ignition switch, no defects noted.					

The aircraft, aircraft engine, propeller, or appliance identified above was repaired and inspected in accordance with current instructions in the approved maintenance manual and Regulations of the Federal Aviation Agency and is approved for return to service.

Permanent details of the repair are on file at Marlboro Aircraft Services, LLC on West Center St. 2340

Certificate # [REDACTED] S AP

Signer

William T. Bienes

Marlboro Aircraft Services, LLC

Reg.#	N-43249	Tach Time	1983.0	Total Time	4178.8
-------	---------	-----------	--------	------------	--------

Performed annual inspection IAW Piper Service Manual, FAA-FAR APP 43 D. Compression test results: Cyl.1-75/80 2-72/80 3-71/80 4-72/80 5-75/80 6-73/80. Oil and filter changed. Filter opened and inspected for contaminants, none found. CH 48110 oil filter installed. Oil sump serviced with 10 qts. 20W-50 Phillips X/C oil. Cleaned fuel screen. Checked magneto timing. Installed BA-3 air filter element. Washed engine and cowling. Lubed all engine controls. Inspected exhaust system, no defects noted. Cleaned, gaped and rotated spark plugs.

AD's Complete to 2012-01A

I certify that on this date 02/04/2012 this engine and propeller have been inspected in accordance with an annual inspection and were determined to be in airworthy condition. Details on file at Marlboro Aircraft Services, LLC on work order # 2354.

AP IA Signed

William J. Blenes

[illegible]

Date 12/20/2011

Farmingdale, NJ 07727

Incl Time	1965.2	Total Time	4161
-----------	--------	------------	------

• with Champion Spark plugs REM38E. Cleaned primer nozzles.
• Ignition switch, no defects noted.

The appliance identified above was repaired and inspected in accordance with the appliance manual and Regulations of the Federal Aviation Agency and is

nt Marlboro Aircraft Services, LLC on Wed Oct 24 23:40

Signed
William T. Bienes

Marlboro Aircraft Services, LLC

7 Highway 34 Farmingdale, NJ 07727

Tach Time	1983.0	Total Time	4178.8
-----------	--------	------------	--------

on IAW Piper Service Manual, FAA-FAR APP 43
s: Cyl.1-75/80 2-72/80 3-71/80 4-72/80 5-75/80
ged. Filter opened and inspected for
CH 48110 oil filter installed. Oil sump serviced
s X/C oil. Cleaned fuel screen. Checked
3A-3 air filter element. Washed engine and
controls. Inspected exhaust system, no defects
d rotated spark plugs.

'04/2012 this engine and propeller have been
h an annual inspection and were determined to
etails on file at Marlboro Aircraft Services, LLC

William J. Bienes

[illegible]

YEAR DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE
3/5/2013	2150.8		4346.6	Mariboro Aircraft Services, LLC Reg.# N-43249 Tach Time 2150.8 Total Time 4346.6 Performed annual inspection IAW Piper Service Manual, FAA-FAR APP 43 D. Compression test results: Cyl. 1-72/80 2-73/80 3-75/80 4-75/80 5-75/80 6-74/80. Changed engine oil and filter. Opened filter and inspected for contaminants, none found. Installed and safety CH-48110 oil filter. Serviced engine sump with 10 qts. 20W-50 Phillips X/C oil. Cleaned, gaped and rotated spark plugs. Checked and set magneto timing. Cleaned fuel screen. Inspected exhaust system, no defects noted. Lubed engine controls. Ground run engine operation normal, no oil leaks noted. C/W AD 2012-19-01 Crankshaft Replacement, no action necessary ICW 2006-20-09 Aircraft returned to service. AD's Complete to 2013-02B. I certify that on this date 03/05/2013 this engine and has been inspected in accordance with an annual inspection and was determined to be in airworthy condition. Details on file at Mariboro Aircraft Services, LLC on work order # 2427. AP IA Signed [Signature] William F. Bienes	1750.4		
Tsmo 2022.4					2165.8		
7/22/13	2209.6			Oil change 66/20W-50 AA48110. AA48110-2 [Signature]			

, Tests, Repairs and Alterations
 me, Rating and Certificate Number of
 3 back pages for other specific entries

Marlboro Aircraft Services, LLC

2150.8 Total Time 4346.6

Service Manual, FAA-FAR APP 43 D.
 73/80 3-75/80 4-75/80 5-75/80
 Opened filter and inspected for
 safety CH-48110 oil filter. Serviced
 s X/C oil. Cleaned, gaped and
 magneto timing. Cleaned fuel screen.
 Lued engine controls. Ground
 s noted.
 ement, no action necessary ICW

is engine and has been inspected in
 and was determined to be in airworthy
 rcraft Services, LLC on work order #

RECORDING
 TACH
 TIME

TODAY'S
 FLIGHT

TOTAL
 TIME IN
 SERVICE

Description of Inspections, Tests, Repairs and Alterations

Entries must be endorsed with Name, Rating and Certificate Number of
 Technician or Repair Facility. (See back pages for other specific entries.)

1798.4

Oil Change Phillips 66/20W-50 10QT
 Filter AA48110-2

Marlboro Aircraft Services, LLC

2165.8

Reg.# N-43249 Tach Time 2294.2 Total Time 4490.0

Performed annual inspection IAW Piper Service Manual, FAA-FAR APP 43D.
 Compression test results: Cyl. 1-74/80 2-75/80 3-75/80 4-75/80 5-74/80
 6-74/80 Changed engine oil and filter. Opened filter and inspected for
 contaminants, none found. Installed CH48110 oil filter. Serviced engine
 sump with 10 qts. 20W-50 Phillips X/C oil. Cleaned, gaped and rotated spark
 plugs. Checked magneto timing. Tighten induction and oil return hose clamps.
 Wash engine and lube all engine controls. Inspected exhaust system, Repair
 heat shroud. Replaced induction air filter element (BA-3). Cleaned fuel Primer
 nozzles. CWAD 04-10-14 no sudden stoppage at this time.
 Aircraft returned to service. AD's Complete to 2014-04B

I certify that on this date 05/01/2014 this engine has been inspected in
 accordance with an annual inspection and was determined to be in airworthy
 condition. Details on file at Marlboro Aircraft Services, LLC on work order #
 3490.

AP IA Signed

William T Blenes

26/20W-50 AA48110

YEAR 2014 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries)	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE
16-26-14	2358			B-1 change A1A48110-2 F:122 C-1 10 Qts Phillips 20W/50	2453.0		
2/2/2015	Tsmo 2285.8			Marlboro Aircraft Services, LLC Reg.# N-43249 Tach Time 2414.2 Total Time 4610.0 Performed annual inspection IAW Piper Service Manual, FAA-FAR APP 43D. Compression test results: Cyl 1-77/80 2-73/80 3-75/80 4-74/80 5-75/80 6-75/80. Changed engine oil and filter. Opened filter and inspected for contaminants, none found. CH48110 oil filter was installed. Engine sump was serviced with 10Qts. 20w-50 Phillips X/C oil. Cleaned, gaped and rotated spark plugs. Inspect left magneto IAW TLMSB No. 537, no defects noted, next due 2664.2 hours. Installed and checked timing of both magnetos. Tighten induction and oil return hose clamps. Washed engine and lower cowl. Inspected exhaust system, repaired heater shroud. Cleaned fuel screen. Replaced induction air filter (BA-3). All AD's in compliance, see compliance report dated 06/02/2015 Aircraft returned to service. I certify that on this date 06/02/2015 this engine has been inspected in accordance with an annual inspection and was determined to be in airworthy condition. Details on file at Marlboro Aircraft Services, LLC on work order # 3545. AP IA Signed William T Bienes	2513.5		

Indorsed with Name, Rating and Certificate Number of
 Fair Facility. (See back pages for other specific entities)

for AA48110-2 F=1 hr
Bob 10 qt ph: 1:05 PM

1717 Highway 34 Farmingdale, NJ 07727

Tach Time	2414.2	Total Time	4610.0
-----------	--------	------------	--------

lion IAW Piper Service Manual, FAA-FAR APP 43D. Compression 2-73/80 3-75/80 4-74/80 5-75/80 6-75/80. Changed engine oil and inspected for contaminants, none found. CH48110 oil filter tp was serviced with 10qts. 20w-50 Phillips X/C oil. Cleaned, plugs. Inspect left magneto IAW TLMSB No. 537, no defects ours. Installed and checked timing of both magnetos. Tighten 350 clamps. Washed engine and lower cowl. Inspected exhaust hood. Cleaned fuel screen. Replaced induction air filter (BA-3).

o compliance report dated 06/02/2015

3.

6/02/2015 this engine has been inspected in accordance with an
determined to be in airworthy condition. Details on file at
LLC on work order # 3545.

William T Bienes

[illegible]

