



RECORD OF CONVERSATION

Robert Gretz
Senior Air Safety Investigator
Eastern Region Aviation

Date: November 25, 2015

Person Contacted: Danny Cox, FAA FSDO, Atlanta, GA

NTSB Accident Number: ERA16LA051

Narrative:

Mr. Cox stated that the flight instructor and student pilot were practicing landings. While in the airport traffic pattern, the engine lost all power and the airplane subsequently impacted wooded terrain. During the impact, both wings separated and the fuel tanks were ruptured. Mr. Cox planned to further examine the engine.