

Rayner Brian

From: Panagiotou Joseph
Sent: Thursday, December 10, 2015 3:50 PM
To: Rayner Brian
Cc: Budinski Michael
Subject: Albany, NY Beech BE-58 ERA16LA052

Brian,

The nose gear fork from the ERA16LA052 accident arrived in the lab today. The fork portion had sustained gross plastic deformation and had fractured into two parts. The fracture surface was consistent with overstress. No evidence of any preexisting conditions that may have contributed to the failure were observed.





