

N6449P
Feb 17, 2016

0-235-L2C
S/N L-16469-15

ENGINE

**Inspected and adjusted valves in accordance with
Lycoming Overhaul and MM.I have inspected work
accomplished and found this engine safe for return to
service at this time.**

Jonathan Escarzaga

A&P 