

# **Aerohead, LLC**

**Mobile, AL**

3 May 2016

Statement of Donald A. Ford, AP [REDACTED] IA

To: Albert L. McCray

I checked that the mixture control had full travel. My helper moved the control inside the aircraft and I verified that it moved from idle cut off to full rich. I performed the same check with the throttle. I performed no maintenance on the mixture or throttle.

During post maintenance, I ran the aircraft twice and was able to lean and secure the engine with the mixture with no problem.

[REDACTED]  
Donald A. Ford