

RECORD OF	☒ VISIT	☐ CONFERENCE OR	☒ TELEPHONE CALL	TIME 9:00	DATE 5/8/16	
NAME (S) OF PERSON (S) CONTACTED OR IN CONFERENCE AND LOCATION					ROUTING	
					SYMBOL	INITIALS
George Nutter						
Property owner [REDACTED]						
[REDACTED] [REDACTED]						
SUBJECT Witness Statement Record of conversation						
DIGEST Mr. Nutter reported to ASI RLC that he was mowing his lawn on the east side of his residence. He did not see the aircraft impact the trees or ground. He had heard a loud thump and when he looked over his shoulder the aircraft was on the ground. He began running to the aircraft and heard the pilot calling for help. He went inside to phone emergency responders. Upon getting back to the aircraft the pilot had already extracted himself from the wreckage. Mr. Nutter assisted the injured pilot by attempting to make him comfortable until emergency personnel arrived. He reported the accident occurred at approximately 1330 hrs and was uncertain how long ^{he} time elapsed before emergency personnel arrived. SEE REVERSE						
CONCLUSION, ACTION TAKEN, OR REQUIRED						
NONE						
DATE 5/9/2016		TITLE ASI R Clark			SIGNATURE [REDACTED]	

Mr. Nutter stated that the wind at the time of the accident was extremely strong but no estimate of speed. The wind was coming from several directions and there was thunderstorm activity north of Rwy 1.