

Triangle
Brick

N 367 FS

Innovative Products. Exceptional Service.

FRONT

INSIDE

OUTSIDE

1A + 1B

BULKHEAD
BEHIND MAIN
GEAR

2A 2B 2C

REAR

LEFT FLOAT FAILURE

trianglebrick.com

sales@trianglebrick.com

800-672-8547