



MEMORANDUM FOR RECORD

**Investigator: Brian C. Rayner
Senior Air Safety Investigator
Eastern Region**

**Date: April 6, 2017
Reference: NTSB Form 6120.1
Pilot: John Secord
NTSB Accident Number: ERA16LA191 Lawrenceburg, Tennessee**

Narrative:

The pilot/operator of the accident airplane did not submit an NTSB Form 6120.1, but he provided records, statements, and other information necessary to complete the investigation. The information was gathered through and by the Federal Aviation Administration (FAA), records, and other means.