


GROMMET WAS NOT INSTALLED
AS REFLECTED



FUEL SYSTEM