RECORD OF ☐ VISIT ☐ CONFERENCE OR ☒ TELEPHONE CALL	TIME 5:30 PM	DATE 08/09/2016

NAME (S) OF PERSON (S) CONTACTED OR IN CONFERENCE AND LOCATION	ROUTING SYMBOL	ROUTING INITIALS
MR. Victor Hendrix [redacted] ASI Rafael Gonzalez		
SO-FSDO-63		
SUBJECT N828BB Accident Investigation Witness Interview		

DIGEST

On August 9, 2016, Mr. Hendrix was identified as a possible witness, this reporting inspector contacted Mr. Hendrix, a resident of St. Croix, Virgin Islands via phone, the witness stated that he did not saw N828BB accident but he lives close by to the airport and he can recognize between low and hi RMP noise from aircraft engines, he explained that around 1120hrs local time he hear a low RMP engine noise approaching the airport consistent with a small aircraft in final approach, suddenly the aircraft engine noise changed to a hi RMP condition between 3 to 5 seconds before a loud crash noise was heard. the witness stated that the hi RPM sound was not interrupted before the loud crash noise or impact.

CONCLUSION, ACTION TAKEN, OR REQUIRED

Send IOP to the NTSB.

DATE	TITLE	SIGNATURE
08/09/2016	ASI	[redacted]