



MEMORANDUM FOR RECORD

Douglass Brazy
Air Safety Investigator
Eastern Region Aviation

August 24, 2016

Subject: METAR weather at the Concord Municipal Airport, Concord, New Hampshire (located about 12 nm west of the accident site) on August 6, 2016

Source: www.ogimet.com

LCL (eastern daylight time) date and time column added

Approximate Accident Time: 1850 eastern daylight time

Query made at 08/24/2016 17:22:01 UTC

Time interval: from 08/06/2016 20:00 to 08/06/2016 23:59 UTC

KCON, Concord, Concord Municipal Airport (United States).

WMO index: 72605. Latitude 43-11-43N. Longitude 071-30-04W. Altitude 105 m.

METAR/SPECI from KCON, Concord, Concord Municipal Airport (United States).			
LCL (EDT)		UTC	
Aug 6 19:51	SA	06/08/2016 23:51->	METAR KCON 062351Z AUTO 35007KT 10SM FEW120 26/17 A2968 RMK A02 SLP049 T02610167 10328 20261 53018=
Aug 6 18:51	SA	06/08/2016 22:51->	METAR KCON 062251Z AUTO 34015KT 10SM FEW090 28/16 A2965 RMK A02 WSHFT 2233 SLP040 T02830161=
Aug 6 17:51	SA	06/08/2016 21:51->	METAR KCON 062151Z AUTO 27009KT 10SM CLR 32/15 A2962 RMK A02 LTG DSNT N SLP028 T03170150=
Aug 6 16:51	SA	06/08/2016 20:51->	METAR KCON 062051Z AUTO 29013G21KT 10SM CLR 32/16 A2962 RMK A02 SLP029 T03170156 56007=

No short TAF reports from **KCON** during solicited interval in the database.

large TAF from KCON, Concord, Concord Municipal Airport (United States).		
FT	06/08/2016 23:20->	TAF KCON 062320Z 0700/0724 33013KT P6SM SCT250 FM070200 30004KT P6SM SKC FM071500 30009G16KT P6SM SCT250=
FT	06/08/2016 20:11->	TAF AMD KCON 062011Z 0620/0718 32012G20KT P6SM VCSH SCT045 SCT080 FM062200 30010KT P6SM SCT050 BKN120 FM070200 31005KT P6SM SCT120 FM071200 31008KT P6SM SCT070=