

NATIONAL TRANSPORTATION SAFETY BOARD EVIDENCE CONTROL	ACCIDENT NUMBER: ERA16LA295
--	---------------------------------------

For Use In All Modal Investigations

OFFICE Aviation Safety	DATE OF ACCIDENT 8/19/16	ACCIDENT LOCATION (City & State) Hollywood, FL
EVIDENCE OBTAINED BY:		
☐ EVIDENCE OBTAINED FROM:	LOCATION OR PERSON INFORMATION	DATE
☒ EVIDENCE RECEIVED FROM:	Florida Air Recovery	9/7/16
EVIDENCE CONTROL NUMBER ERA16LA295 - IIC - 001	455 Tresca Road Jacksonville, FL 32225	GROUP
DESCRIPTION (☐ BIN ITEM - HAS BEEN SEPARATED ☐ right propeller hub assy. - N16499		

OWNER OR OWNER'S REPRESENTATIVE

FIRST NAME:	LAST NAME: American Flight Training LLC
ADDRESS: 14351 NW 41 Ave Opa Locka, FL 33054	
PHONE:	EMAIL:
RETURNED ☒	DATE: 1/27/17
CONTACT: Michael O'Shea at Florida Air Recovery	

CHAIN OF CUSTODY

RELEASED BY: Florida Air	RELEASED TO: NTSB Materials LAB	DATE: 9/7/16
PURPOSE: Exam		
RELEASED BY: NTSB Materials LAB	RELEASED TO: Florida Air Recovery	DATE: 1/27/17
PURPOSE:		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		
RELEASED BY:	RELEASED TO:	DATE:
PURPOSE:		

**NATIONAL TRANSPORTATION SAFETY BOARD
MATERIALS LABORATORY DIVISION
RECEIPT OF RETURNED PARTS**

ACCIDENT/INCIDENT IDENTIFICATION		
PLACE:	Hollywood, FL	
DATE / VEHICLE:	August 19, 2016	Piper PA-34-200, N16499
NTSB NO. / IIC:	ERA16LA295	Doug Brazy, AS-ERA
THE FOLLOWING PARTS, PIECES OR COMPONENTS, FROM THE ABOVE ACCIDENT/INCIDENT		
-Fractured housing fragments (2) <u>16 lbs.</u> -Fracture surface section -Hardness testing section -Drive shaft assembly		
ARE BEING RETURNED VIA U.S. REGISTERED MAIL NO.:		
OR BY OTHER CARRIER (NAMED)		UPS: <u>1ZA4E7150393788356</u>
WHICH HAS BEEN ADDRESSED TO:		
NAME :	Michael O'Shea	
COMPANY:	Florida Air Recovery	
ADDRESS :	455 Tresca Rd	
	Jacksonville, FL 32225	

RECIPIENTS PLEASE VERIFY THAT THE COMPONENTS, AS ITEMIZED, HAVE BEEN RECEIVED BY PRINTING LEGIBLE YOUR NAME, SIGNING, AND DATING THIS FORM BELOW, AND RETURNING THIS DOCUMENT TO: *Mike Budinski, CHIEF, MATERIALS LABORATORY DIVISION, (RE-30), NATIONAL TRANSPORTATION SAFETY BOARD, 490 L'ENFANT PLAZA EAST, WASHINGTON, D.C. 20594.* ATTACHED IS A SELF-ADDRESSED, FRANKED ENVELOPE FOR YOUR CONVENIENCE.
IF ANY DISCREPANCIES ARE FOUND, IMMEDIATELY CALL (202) 314-6530.

WRITER'S NAME AND INITIALS	Mueller, Erik M	DATE	01/24/2017
NTSB REPRESENTATIVE PACKING PARTS	Mueller, Erik M	DATE	01/24/2017
NAME AND SIGNATURE OF RECIPIENT OR RECIPIENT'S REPRESENTATIVE	Print Sign	DATE	

Part Return Form.doc (Word Template)

Brazy Doug

From: Boggs Daniel
Sent: Wednesday, September 7, 2016 2:13 PM
To: Brazy Doug
Subject: parts shipped

Mr. Brazy Sir!!!!
Your parts have been shipped to the lab,

Waiting further orders for engine exam/teardown!

Have a nice day sir...

Daniel Boggs
Air Safety Investigator
National Transportation Safety Board
45065 Riverside Parkway
Ashburn, VA 20147



Proof of Delivery

[Close Window](#)

Dear Customer,

This notice serves as proof of delivery for the shipment listed below.

Tracking Number:	1ZA4E7150393788356
Service:	UPS Ground
Weight:	16.00 lbs
Shipped/Billed On:	01/24/2017
Delivered On:	01/27/2017 4:46 P.M.
Delivered To:	JACKSONVILLE, FL, US
Received By:	RICKS
Left At:	Reception

Thank you for giving us this opportunity to serve you.

Sincerely,

UPS

Tracking results provided by UPS: 02/17/2017 3:00 P.M. ET

[Print This Page](#)[Close Window](#)