



Figure 1 Front view of the gyrocopter laying on its left side



Figure 2 The adjusted prerotator motor after the accident