



Weather Observations

Heidi Kemner
Air Safety Investigator
Eastern Region Aviation

December 23, 2016

SA	23/12/2016 22:15- >	METAR K6B0 232215Z AUTO 15005KT 10SM CLR 02/M04 A3028 RMK AO2 T00201045=
SA	23/12/2016 21:55- >	METAR K6B0 232155Z AUTO 17007KT 10SM CLR 02/M04 A3027 RMK AO2 T00241043=
SA	23/12/2016 21:35- >	METAR K6B0 232135Z AUTO 16007KT 10SM CLR 03/M04 A3028 RMK AO2 T00251040=
SA	23/12/2016 21:15- >	METAR K6B0 232115Z AUTO 16006G15KT 10SM CLR 03/M04 A3027 RMK AO2 T00261037=
SA	23/12/2016 20:55- >	METAR K6B0 232055Z AUTO 17008KT 10SM CLR 03/M04 A3027 RMK AO2 T00301036=
SA	23/12/2016 20:35- >	METAR K6B0 232035Z AUTO 19009KT 10SM CLR 03/M03 A3026 RMK AO2 T00331035=
SA	23/12/2016 20:15- >	METAR K6B0 232015Z AUTO 19007KT 10SM CLR 04/M03 A3027 RMK AO2 T00351032=
SA	23/12/2016 19:55- >	METAR K6B0 231955Z AUTO 18007KT 10SM CLR 04/M03 A3026 RMK AO2 T00381030=
SA	23/12/2016 19:35- >	METAR K6B0 231935Z AUTO 19011G14KT 10SM CLR 04/M03 A3026 RMK AO2 T00401032=
SA	23/12/2016 19:15- >	METAR K6B0 231915Z AUTO 21008KT 170V230 10SM CLR 04/M03 A3026 RMK AO2 T00411026=
SA	23/12/2016 18:55- >	METAR K6B0 231855Z AUTO 19009KT 10SM CLR 04/M03 A3025 RMK AO2 T00401026=
SA	23/12/2016 18:35- >	METAR K6B0 231835Z AUTO 17008G14KT 10SM CLR 04/M02 A3025 RMK AO2 T00401024=
SA	23/12/2016 18:15- >	METAR K6B0 231815Z AUTO 15009KT 120V180 10SM SCT028 04/M02 A3025 RMK AO2 T00361024=
SA	23/12/2016 17:55- >	METAR K6B0 231755Z AUTO 15005G14KT 10SM CLR 04/M02 A3025 RMK AO2 T00361025 10037 21032=
SA	23/12/2016 17:35- >	METAR K6B0 231735Z AUTO 18008KT 10SM SCT025 03/M02 A3025 RMK AO2 T00331025=
SA	23/12/2016 17:15- >	METAR K6B0 231715Z AUTO 17007KT 140V200 10SM SCT025 SCT031 03/M03 A3025 RMK AO2 T00301027=
SA	23/12/2016 16:55- >	METAR K6B0 231655Z AUTO 17009G15KT 10SM CLR 03/M03 A3026 RMK AO2 T00301028=
SA	23/12/2016 16:35- >	METAR K6B0 231635Z AUTO 18011G14KT 10SM SCT032 03/M03 A3026 RMK AO2 T00271031=
SA	23/12/2016 16:15- >	METAR K6B0 231615Z AUTO 17008KT 10SM SCT032 03/M04 A3027 RMK AO2 T00271036=
SA	23/12/2016 15:55- >	METAR K6B0 231555Z AUTO 17010KT 150V210 10SM CLR 03/M04 A3027 RMK AO2 T00251037=

SA	23/12/2016 15:35- >	METAR K6B0 231535Z AUTO 18006KT 10SM CLR 02 / M04 A3028 RMK AO2 T00211037=
SA	23/12/2016 15:15- >	METAR K6B0 231515Z AUTO 17006KT 10SM CLR 02 / M04 A3027 RMK AO2 T00191040=
SA	23/12/2016 14:55- >	METAR K6B0 231455Z AUTO 17008KT 10SM CLR 02 / M04 A3027 RMK AO2 T00161041=
SA	23/12/2016 14:35- >	METAR K6B0 231435Z AUTO 15007KT 10SM CLR 01 / M04 A3027 RMK AO2 T00111040=
SA	23/12/2016 14:15- >	METAR K6B0 231415Z AUTO 17004KT 10SM CLR 01 / M04 A3027 RMK AO2 T00081040=
SA	23/12/2016 13:55- >	METAR K6B0 231355Z AUTO 16005KT 10SM CLR 00 / M04 A3026 RMK AO2 T00021041=
SA	23/12/2016 13:35- >	METAR K6B0 231335Z AUTO 15004KT 10SM CLR 00 / M03 A3025 RMK AO2 T100111029=
SA	23/12/2016 13:15- >	METAR K6B0 231315Z AUTO 15003KT 10SM CLR M01 / M02 A3025 RMK AO2 T101111019=
SA	23/12/2016 12:55- >	METAR K6B0 231255Z AUTO 14004KT 10SM CLR M01 / M01 A3025 RMK AO2 T101411015=
SA	23/12/2016 12:35- >	METAR K6B0 231235Z AUTO 16004KT 10SM CLR M02 / M02 A3024 RMK AO2 T10191022=