

YEAR 2015	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
# 2595.3A	158.0			
		Country Line Aviation [Redacted] Keystone Heights Airport Starke, FL 32091		Date: 10-3-2015 TACH: 158.0
	340 H 171.00	Cessna 182		
		M1839X		
				ENGINE
				I certify that this engine has been inspected in accordance with an annual inspection and has been determined to be in airworthy condition and is recommended for return to service. During this inspection the following work was accomplished. Compression checks are as follows: # 1 = 76/80, # 2 = 70/80, # 3 = 76/80, # 4 = 72/80, # 5 = 76/80, # 6 = 70/80 Changed oil and oil filter, this engine was serviced with 12 Qts Aeroshell 15W-50 oil and a Champion CH48110-1 oil filter. Spark plugs were cleaned and gapped and three (3) new RH4M 40E plugs replaced with new. Ignition timing was set using Time rite instrument. To 22° BTc as per manual for O-470 R. Replaced bracket air filter element with P/N BA8103-1. This engine was run-up and checked for leaks and proper operation ("OPS checked normal")
				AD's were reviewed and are current to date. (T-Date Rev. 2015 Kenneth R. Oddy /A&P [Redacted] Signed [Signature]

[illegible]

YEAR 20	TACH TIME	TODAY'S FLIGHT TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
		County Line Aviation [Redacted] Keystone Heights Airport Starke, FL 32091 Cessna 182 N1839K	Date: 10-3-2015 TACH: 158.0
		AIRFRAME	
		I certify that this airframe has been inspected in accordance with an annual inspection and has been determined to be in airworthy condition and is recommended for return to service. During this inspection the following work was accomplished. Removed all 3 wheels and cleaned and inspected wheel bearings and races. Repacked with grease and re-assembled. Brake linings inspected and system serviced with Mil-spec 5606 Hyd Fluid. Aircraft was serviced with ACF-50 corrosion treatment.	
		AD's were reviewed and are current to date. (I-Date Rev. 2015) Kenneth R. Oddy, [Redacted]	
		Signed [Redacted] [Signature]	

YEAR 20	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Entries must be endorsed with Name, Rating and Certificate Technician or Repair Facility. (See back pages for other spec
		County Line Aviation		Date: 10-9-15 TACH: 158.0
		Keystone Heights Airport		
		Starke, FL 32091		
		M1839X		
		Cessna 182		
		Fit wing tips to airplane, drill mounting holes, prime, paint And install strobe lights		
		AD's were reviewed and are current to date.		
		(T-Date Rev. 2015		
		Kenneth R. Oddy, A&P		
		Signature: [Redacted]		