

		Blue Line Technical Services, LLC		
		Smithfield NC, 27577		Airframe
Make: Beechcraft		Model: B60		3/2/2017
Reg. No. N39AG		Serial No.: P-425		
TT: 3271.6		Hobbs: 3271.6		
Work Performed: Annual Inspection IAW FAR 43 Appendix (d) and Beechcraft 100hr checklist. Removed ELT and sent for repair. All control surfaces inspected and attach points lubricated. Checked all nav, landing, and interior lightings for operation. Inspected brake system. Inspected flap systems cleaned and lubed. Serviced Accumulators. Replaced right generator current limiter boot. CW AD 2004-25-16R1 checked no leaks noted, next due 3371.6 Hobbs or 2 years. C/W AD 2004-21-05 no dects noted. All AD's checked for compliance. I certify that I have inspected this aircraft IAW a Annual Inspection and have found it to be in an airworthy condition on this date.				
Marvin Urbina A&P				3/2/2017
Name/ Certificate No.		Signature		Date

		Blue Line Technical Services, LLC		RIGHT
		Smithfield NC, 27577		Engine
Make: Beechcraft		Model: B60		3/2/2017
Reg. No. N39AG		Model: Lycoming TIO-541-E1C4		Serial: L-1621-59
TT 3417.1		SMOH: 1588.6		Hobbs: 3271.6
Work Performed: Annual Inspection on this date IAW FAR 43 Appendix (d) and Lycoming Service Info. Compression as follows #1-78 #2-77 #3-76 #4-76 #5-78 #6-76. Changed oil and filter. Serviced with 11 qts Aeroshell 15w50 and oil filter PN#CH48104. Filter cut for particle inspection. None Found. Oil analysis pulled. Plugs, cleaned, inspected, gapped. External mag timing verified. Added two 12oz Bottles of AVBLEND additive. Tighten intercooler brace hardware. All AD's checked for compliance. Engine cleaned, test run and leak checked. All conditions normal. I certify that I have inspected this engine IAW Annual Inspection and have found it to be in an airworthy condition on this date.				
Marvin Urbina A&P				3/2/2017
Name/ Certificate No.		Signature		Date

		Blue Line Technical Services, LLC		RIGHT
[Redacted]		[Redacted]		
Smithfield NC, 27577		Propeller		
Make: Beechcraft		Model: B60		3/2/2017
Reg. No. N39AG		Model: HC-F3YR-2UF		Serial: DA1137
TT	3271.6	TSPOH:	1888.8	Hobbs: 3271.6
<u>Work Performed:</u> Annual Inspection. Removed spinner and bulkhead. Checked for security and leakage. Reinstalled spinner. All AD's checked for compliance. I certify that I have inspected this prop IAW an Annual Inspection and have found it to be in an airworthy condition on this date.				
Marvin Urbina A&P [Redacted]		[Redacted]		3/2/2017
Name/ Certificate No.		Signature		Date

		Blue Line Technical Services, LLC		LEFT
[Redacted]		[Redacted]		
Smithfield NC, 27577		Engine		
Make: Beechcraft		Model: B60		3/2/2017
Reg. No. N39AG		Model: Lycoming TIO-541-E1C4		Serial: L-1333-59
TT	3523.9	SMOH:	454.9	Hobbs: 3271.6
<u>Work Performed:</u> Annual Inspection on this date IAW FAR 43 Appendix (d) and Lycoming Service Info. Compression as follows #1-78 #2-78 #3-79 #4-76 #5-76 #6-76. Changed oil and filter. Serviced with 11 qts Aeroshell 15w50 and oil filter PN#CH48104. Filter cut for particle inspection. None Found. Oil analysis pulled. Plugs, cleaned, inspected, gapped. External mag timing verified. Added two 12oz Bottles of AVBLEND additive. Tighten turbo drain tube hardware. All AD's checked for compliance. Engine cleaned, test run and leak checked. All conditions normal. I certify that I have inspected this engine IAW Annual Inspection and have found it to be in an airworthy condition on this date.				
Marvin Urbina [Redacted]		[Redacted]		3/2/2017
Name/ Certificate No.		Signature		Date

		Blue Line Technical Services, LLC		LEFT
[Redacted]		[Redacted]		
Smithfield NC, 27577		Propeller		
Make: Beechcraft		Model: B60		3/2/2017
Reg. No. N39AG		Model: HC-F3YR-2UF		Serial: DA1138
TT	3271.6	TSPOH:	1888.8	Hobbs: 3271.6
<u>Work Performed:</u> Annual Inspection. Removed spinner and bulkhead. Checked for security and leakage. Reinstalled spinner. All AD's checked for compliance. I certify that I have inspected this prop IAW an Annual Inspection and have found it to be in an airworthy condition on this date.				
Marvin Urbina A&P [Redacted]		[Redacted]		3/2/2017
Name/ Certificate No.		Signature		Date

Blue Line Technical
Services, LLC

Raleigh, NC 27675



INVOICE

BILL TO

Brad Mutchler

INVOICE # 1477

DATE 03/02/2017

DUE DATE 03/02/2017

TERMS Due on receipt

ACTIVITY	QTY	RATE	AMOUNT
Annual Inspection	1	2,500.00	2,500.00
Labor Performed: Tightened right engine lower outboard intercooler brace hardware. Removed ELT and sent for repair. Serviced accumulators. Replaced right generator current limiter boot. Removed heater, performed decay test and resealed fuel nozzle gasket, reinstalled. Tightened loose riv nuts. Tightened loose bolt on left turbo drain. Replaced multiple velcro on carpet. Troubleshoot and replaced fuse for cigar lighter.	9	85.00	765.00
Aeroshell Oil	22	9.50	209.00T
Oil Filter	2	29.95	59.90T
Avblend Oil Additive	4	18.50	74.00T
Oil Analysis Kit	2	29.99	59.98T
Battery Boot	1	1.99	1.99T
Grommet	1	0.50	0.50T
Boot Dressing	1	35.00	35.00
Velcro	1	30.00	30.00
USB cigar lighter adapter	1	30.00	30.00
Fuse	1	2.99	2.99
Lubricants, Solvents, grease and shop supplies	1	35.00	35.00

Please remit payment to:
Blue Line Technical Services
Raleigh, NC 27675

SUBTOTAL	3,803.36
TAX (6.75%)	27.37
TOTAL	3,830.73
PAYMENT	3,830.73
BALANCE DUE	\$0.00