

March 28, 2017

National Transportation Safety Board
Timothy W. Morville

I, Michael L. Plez, General Manager of Sturdivant Brothers Flying Service, Inc. used the same fuel in a AT802 plane that we used in Sturdivant Brothers Flying Service, Inc. AT602 plane. There is not any issue with the AT802 plane. (N2060H) [REDACTED]

Also attached is a copy of Valero Refining Company's Certificate of Analysis dated 2/13/17.

Michael L. Plez

[REDACTED]