

**Tennessee Aircraft Services, Inc.**

2313 Technology Center Drive
Jackson, TN 38301
Phone: 731-424-7227
Email: [REDACTED]
Date: 2/17/2017, 2:23 PM

CUSTOMER INFORMATION**RHEIORG Consulting LLC**

[REDACTED]
Reg. No: 6563D
1974 CESSNA T210L
Current A/C TT: 4288.2, Tach: 2250.5
A/C Serial: 21060580
Terms: NET30

Customer Invoice**Work Order: 7433****Item: 1 - Customer Recommended****Discrepancy**

Oil change Tach:2250.5

Hours

2.46

Subtotal

221.40

Corrective Action

Drained oil sump and took oil sample for analysis. Removed oil filter and cut for inspection with no problems noted. Installed drain plug with new seal p/n MS35769-11 and safetied. Installed new oil filter p/n AA48109 and serviced engine with nine quarts of Aeroshell W100 and one pint of Camguard. Engine ground check run satisfactory.

Inspection Information:

Final Inspector: DAVID CARTER on 02/15/17

Qty	Unit	Part Number	Description	Serial Number	Unit Price	Subtotal
1	EA	AA48109	OIL FILTER (P/O: 4014) (Taxed)		21.55	21.55
9	EA	Aero W100	Aeroshell oil W100 (P/O: 3977) (Taxed)		7.42	66.78
1	EA	CAMGUARD	OIL ADDITIVE (P/O: 4101) (Taxed)		32.00	32.00
1	EA	MS35769-11	CRUSH GASKET (P/O: 4078) (Taxed)		1.47	1.47
1	EA	Oil Analysis Kit	Oil Analysis Kit (P/O: 4015) (Taxed)		30.00	30.00

Labor: \$221.40**Parts: \$151.80****Shipping: \$0.00****Item Subtotal:****\$373.20**

Please see the next page for the totals for this invoice

Additional Charges							
Pilot Services	Tire Disposal	Hazmat	Oil Analysis	Shop Supplies	Fuel	Misc.	Subtotal
0.00	0.00	0.00	0.00	4.43	0.00	0.00	\$4.43

Labor Summary	
Shop Labor: \$221.40	Outside Repair: \$0.00

Taxed Items:
 Hazmat, Shop Labor, OSR Labor, Misc. Charges, Oil Analysis, Shop Parts, OSR Parts, ,
 Shipping In, Shipping Out, Shop Supplies, Tire Disposal

Tax Breakdown: (Before Calculated)

Hazmat: 0.00
 Shop Labor: 221.40
 OSR Labor: 0.00
 Misc. Charges: 0.00
 Oil Analysis: 0.00
 Shop Parts: 151.80
 OSR Parts: 0.00
 : 0.00
 Shipping In: 0.00
 Shipping Out: 0.00
 Shop Supplies: 4.43
 Tire Disposal: 0.00

Total Labor:	\$221.40
Total Parts:	\$151.80
Total Shipping:	\$0.00
Additional Charges:	\$4.43
Tax:	\$36.82
Amount Due:	\$414.45
Deposit:	\$0.00
Balance Due:	\$414.45

Important Information

We appreciate your business!
 Payment is due in full at time of aircraft delivery.

A finance charge of 1.5% per month will be applied to all accounts that are 30 days past due. (1.5% per month is 18% per annum)

A 2.5% charge will be added for payment by credit card.

RHEIORG Consulting LLC or Authorized Representative

Date

MAKE: CESSNA
MODEL: T210L
S/N: 21060580
REG. NO: 6563D
WORK ORDER: 7258



Tennessee Aircraft Services, Inc.

2313 Technology Center Drive
Jackson, TN 38301
Phone: 731-424-7227

DATE: 25 July, 2016
A/C TSN: 4265.4
TACH: 2227.7

Airframe Entries

- Installed new starter solenoid, p/n: 8781-8, and operational check was good.
- Installed new instrument panel lighting day/night toggle switch, p/n: MTA-206N.

DATE: 25 July, 2016

SIGNED:

Work Order: 7258

David Carter, 

Printed by EBis 3 (datcomedia.com)

ENGINE MODEL:
TSIO-520-R9B
ENGINE S/N: 293832R
REG. NO: 6563D
WORK ORDER: 7337

**Tennessee Aircraft Services, Inc.**

2313 Technology Center Drive
Jackson, TN 38301
Phone: 731-424-7227

DATE: 04 October, 2016
A/C TSN: 4277.9
ENG TT: 912.9
TSMOH:
TACH: 2240.2

Engine Entries

- Cleaned and reinstalled #1 lower spark plug. Operational check was good.
 - Installed new EGT probe p/n: M-111, on #1 cylinder. Operational check was good.
-

DATE: 04 October, 2016

SIGNED:

Work Order: 7337

David Carter, 

Printed by EBis 3 (datcomedia.com)

ENGINE MODEL:
TSIO-520-R9B
ENGINE S/N: 293832R
REG. NO: 6563D
WORK ORDER: 7337

**Tennessee Aircraft Services, Inc.**

2313 Technology Center Drive
Jackson, TN 38301
Phone: 731-424-7227

DATE: 04 October, 2016
A/C TSN: 4277.9
ENG TT: 912.9
TSMOH:
TACH: 2240.2

Engine Entries

- Cleaned and reinstalled #1 lower spark plug. Operational check was good.
 - Installed new EGT probe p/n: M-111, on #1 cylinder. Operational check was good.
-

DATE: 04 October, 2016

SIGNED:

Work Order: 7337

David Carter, 

Printed by EBis 3 (datcomedia.com)

MAKE: CESSNA
MODEL: T210L
S/N: 21060580
REG. NO: 6563D
WORK ORDER: 7352

**Tennessee Aircraft Services, Inc.**

2313 Technology Center Drive
Jackson, TN 38301
Phone: 731-424-7227

DATE: 21 October, 2016
A/C TSN: 4293.4
TACH: 2255.7

Airframe Entries

- Installed new TIT probe p/n M-111. Ops checks good.
 - Installed new voltage regulator p/n: R25101 s/n: 511045 in accordance with Zeftronics installation instructions. Ops checked good.
 - Work performed by Nat Crenshaw, Blake Sides and Paul New.
-

DATE: 21 October, 2016

SIGNED:

Work Order: 7352

Paul New, 

Printed by EBis 3 (datcomedia.com)