



MEMORANDUM FOR RECORD

Brian C. Rayner
Senior Air Safety Investigator
Eastern Region Aviation

March 26, 2018

Subject: ERA17FA140 Dadeville, Alabama
Name: Joel Clark – Clay Perkins – Federal Aviation Administration

Mssrs. Clark and Perkins participated in the on-scene portion of the investigation, as well as off-site examination of the engine and the airplane's maintenance records.

Mr. Perkins reviewed the maintenance records of the airplane going back 10 years. These records included a comprehensive sudden-stoppage inspection performed by an aircraft engine shop due to a propeller-strike event. Mr. Perkins' review of these records and the work order for the inspection revealed no anomalies.

Mr. Clark attended a detailed disassembly inspection of the airplane's engine at the manufacturer's facility in Mobile, Alabama. At the completion of the exam, the manufacturer published a report. Mr. Clark reviewed the report and concurred with its findings.

Mr. Clark also attended the propeller exam which was performed by a representative of the propeller manufacturer at the engine manufacturer's facility. The representative prepared a report which Mr. Clark reviewed, and he concurred with its findings.