




Name	ModeC	Name2	Mode3	Latitude	Longitude	F7
3:30:32 PM	8200	8100T	3606	38:59:30.30N	80:12:02.38W	0
3:30:46 PM	8200	8100T	3606	38:59:59.95N	80:12:09.79W	0
3:31:28 PM	8200	8100T	3606	39:01:20.24N	80:12:55.39W	0
3:30:51 PM	8200	8100T	3606	39:00:07.53N	80:12:03.67W	0
3:30:55 PM	0	0T	3606	39:00:18.50N	80:12:11.50W	0
3:31:00 PM	8200	8100T	3606	39:00:26.79N	80:12:03.31W	0
3:31:05 PM	0	0T	3606	39:00:33.34N	80:12:15.07W	0
3:31:14 PM	8200	8100T	3606	39:00:51.14N	80:12:31.93W	0
3:31:19 PM	8200	8100T	3606	39:01:02.83N	80:12:26.36W	0
3:31:24 PM	8200	8100T	3606	39:01:10.02N	80:12:39.81W	0
3:31:09 PM	8200	8100T	3606	39:00:45.35N	80:12:05.15W	0
3:30:13 PM	8200	8100T	3606	38:59:06.54N	80:11:21.76W	0
3:30:18 PM	8100	8000T	3606	38:59:09.93N	80:11:24.59W	0
3:30:22 PM	8200	8100T	3606	38:59:17.52N	80:11:27.91W	0
3:30:41 PM	8200	8100T	3606	38:59:49.54N	80:11:52.68W	0
3:30:27 PM	8200	8100T	3606	38:59:28.52N	80:11:33.98W	0
3:30:37 PM	8200	8100T	3606	38:59:43.80N	80:11:31.15W	0
3:30:04 PM	8200	8100T	3606	38:58:58.50N	80:10:41.93W	0
3:30:08 PM	8200	8100T	3606	38:59:06.95N	80:10:36.03W	0
3:36:49 PM	8200	8100T	3606	39:11:31.41N	80:20:00.04W	0
3:36:54 PM	8200	8100T	3606	39:11:41.00N	80:20:02.37W	0
3:36:58 PM	8200	8100T	3606	39:11:47.60N	80:20:05.67W	0
3:40:40 PM	8200	8100T	3606	39:19:10.14N	80:25:14.63W	0
3:40:59 PM	8200	8100T	3606	39:19:51.71N	80:25:36.88W	0
3:40:45 PM	8100	8000T	3606	39:19:21.47N	80:25:19.22W	0
3:40:50 PM	8200	8100T	3606	39:19:31.35N	80:25:24.30W	0
3:40:54 PM	8200	8100T	3606	39:19:39.70N	80:25:28.50W	0
3:41:51 PM	8200	8100T	3606	39:21:17.56N	80:26:39.36W	0
3:41:56 PM	8200	8100T	3606	39:21:28.45N	80:26:41.83W	0
3:42:00 PM	8200	8100T	3606	39:21:33.74N	80:26:49.80W	0
3:42:05 PM	8200	8100T	3606	39:21:52.21N	80:26:54.22W	0
3:42:10 PM	8100	8000T	3606	39:21:57.77N	80:26:57.11W	0
3:42:14 PM	8100	8000T	3606	39:22:03.41N	80:27:04.77W	0
3:42:19 PM	8100	8000T	3606	39:22:22.49N	80:27:08.01W	0
3:41:13 PM	8100	8000T	3606	39:20:11.57N	80:25:54.04W	0
3:41:18 PM	8100	8000T	3606	39:20:24.01N	80:25:57.64W	0
3:41:32 PM	8200	8100T	3606	39:20:54.83N	80:26:11.13W	0
3:41:37 PM	8200	8100T	3606	39:21:00.52N	80:26:19.26W	0
3:41:41 PM	8200	8100T	3606	39:21:09.10N	80:26:27.36W	0
3:41:23 PM	8200	8100T	3606	39:20:39.96N	80:25:59.40W	0
3:41:27 PM	8200	8100T	3606	39:20:44.54N	80:26:07.89W	0
3:41:04 PM	8200	8100T	3606	39:19:52.85N	80:25:42.21W	0
3:41:08 PM	8100	8000T	3606	39:20:07.45N	80:25:45.25W	0
3:41:46 PM	8200	8100T	3606	39:21:14.28N	80:26:30.74W	0
3:38:56 PM	8200	8100T	3606	39:15:48.57N	80:22:56.31W	0
3:39:01 PM	0	0T	3606	39:15:51.14N	80:22:57.91W	0

3:38:47 PM	8200 8100T	3606 39:15:22.71N	80:22:38.71W	0
3:38:51 PM	8200 8100T	3606 39:15:35.22N	80:22:47.55W	0
3:39:15 PM	8200 8100T	3606 39:16:19.88N	80:23:19.22W	0
3:39:20 PM	0 0T	3606 39:16:30.62N	80:23:24.52W	0
3:39:29 PM	8200 8100T	3606 39:16:50.45N	80:23:38.97W	0
3:39:34 PM	8200 8100T	3606 39:16:57.39N	80:23:41.71W	0
3:39:39 PM	8200 8100T	3606 39:17:06.19N	80:23:49.82W	0
3:39:44 PM	8200 8100T	3606 39:17:13.25N	80:23:52.26W	0
3:39:25 PM	8200 8100T	3606 39:16:38.74N	80:23:28.26W	0
3:39:06 PM	8200 8100T	3606 39:15:59.55N	80:23:02.99W	0
3:39:11 PM	8200 8100T	3606 39:16:11.30N	80:23:09.66W	0
3:38:14 PM	8200 8100T	3606 39:14:21.05N	80:21:57.48W	0
3:38:18 PM	8200 8100T	3606 39:14:26.23N	80:22:02.62W	0
3:38:00 PM	8200 8100T	3606 39:13:49.07N	80:21:34.77W	0
3:37:46 PM	8200 8100T	3606 39:13:22.32N	80:21:15.32W	0
3:37:50 PM	8200 8100T	3606 39:13:31.59N	80:21:19.71W	0
3:37:55 PM	8200 8100T	3606 39:13:41.74N	80:21:32.35W	0
3:38:05 PM	8200 8100T	3606 39:13:57.47N	80:21:38.25W	0
3:38:09 PM	8200 8100T	3606 39:14:09.72N	80:21:51.69W	0
3:37:17 PM	8200 8100T	3606 39:12:25.64N	80:20:41.70W	0
3:37:36 PM	8200 8100T	3606 39:13:05.21N	80:21:05.35W	0
3:37:41 PM	8200 8100T	3606 39:13:10.41N	80:21:05.84W	0
3:37:22 PM	8200 8100T	3606 39:12:39.06N	80:20:48.60W	0
3:37:26 PM	8200 8100T	3606 39:12:44.79N	80:20:50.27W	0
3:37:31 PM	8200 8100T	3606 39:12:52.94N	80:20:54.39W	0
3:37:03 PM	8200 8100T	3606 39:11:59.10N	80:20:19.59W	0
3:37:08 PM	8200 8100T	3606 39:12:07.75N	80:20:19.40W	0
3:37:12 PM	8200 8100T	3606 39:12:17.59N	80:20:27.89W	0
3:38:28 PM	8200 8100T	3606 39:14:47.42N	80:22:15.69W	0
3:38:33 PM	8200 8100T	3606 39:14:55.78N	80:22:22.91W	0
3:38:38 PM	8200 8100T	3606 39:15:09.20N	80:22:28.38W	0
3:38:42 PM	8200 8100T	3606 39:15:14.69N	80:22:32.66W	0
3:38:23 PM	8200 8100T	3606 39:14:39.18N	80:22:08.22W	0
3:40:12 PM	8100 8000T	3606 39:18:13.80N	80:24:36.04W	0
3:40:17 PM	8100 8000T	3606 39:18:26.35N	80:24:43.21W	0
3:39:48 PM	8200 8100T	3606 39:17:30.98N	80:24:02.45W	0
3:40:02 PM	8200 8100T	3606 39:17:58.97N	80:24:24.07W	0
3:40:07 PM	8200 8100T	3606 39:18:05.19N	80:24:29.92W	0
3:40:26 PM	8200 8100T	3606 39:18:44.41N	80:24:54.25W	0
3:40:31 PM	8200 8100T	3606 39:18:51.29N	80:24:59.36W	0
3:40:35 PM	8200 8100T	3606 39:19:01.44N	80:25:05.18W	0
3:33:49 PM	8200 8100T	3606 39:05:47.69N	80:15:59.57W	0
3:34:04 PM	8200 8100T	3606 39:06:12.08N	80:16:19.38W	0
3:34:18 PM	8200 8100T	3606 39:06:40.14N	80:16:30.97W	0
3:33:59 PM	8200 8100T	3606 39:06:02.73N	80:15:58.86W	0
3:34:08 PM	8200 8100T	3606 39:06:23.04N	80:16:14.27W	0
3:34:13 PM	8100 8000T	3606 39:06:31.25N	80:16:17.40W	0

3:33:17 PM	8200 8100T	3606 39:04:41.11N	80:15:24.58W	0
3:33:26 PM	8200 8100T	3606 39:05:03.24N	80:15:22.36W	0
3:33:31 PM	8200 8100T	3606 39:05:11.54N	80:15:29.86W	0
3:33:35 PM	8200 8100T	3606 39:05:18.40N	80:15:24.11W	0
3:33:07 PM	8200 8100T	3606 39:04:24.78N	80:14:59.84W	0
3:33:12 PM	8200 8100T	3606 39:04:32.30N	80:15:06.26W	0
3:33:03 PM	8200 8100T	3606 39:04:16.71N	80:14:53.33W	0
3:33:21 PM	8200 8100T	3606 39:04:51.38N	80:15:15.00W	0
3:33:45 PM	8100 8000T	3606 39:05:39.09N	80:15:51.14W	0
3:33:54 PM	8200 8100T	3606 39:05:54.56N	80:15:55.34W	0
3:33:40 PM	8200 8100T	3606 39:05:30.08N	80:15:27.80W	0
3:34:55 PM	8200 8100T	3606 39:07:49.13N	80:17:22.74W	0
3:35:38 PM	8200 8100T	3606 39:09:12.90N	80:18:22.26W	0
3:35:28 PM	8200 8100T	3606 39:08:52.25N	80:18:02.92W	0
3:35:33 PM	8200 8100T	3606 39:09:01.49N	80:18:09.87W	0
3:35:10 PM	8200 8100T	3606 39:08:16.13N	80:17:40.76W	0
3:35:14 PM	8200 8100T	3606 39:08:27.36N	80:17:41.03W	0
3:35:19 PM	8200 8100T	3606 39:08:34.42N	80:17:53.53W	0
3:35:00 PM	8200 8100T	3606 39:08:01.71N	80:17:27.35W	0
3:35:05 PM	8200 8100T	3606 39:08:10.48N	80:17:34.30W	0
3:35:24 PM	8200 8100T	3606 39:08:42.18N	80:17:54.68W	0
3:36:21 PM	8200 8100T	3606 39:10:36.93N	80:19:21.97W	0
3:35:57 PM	8200 8100T	3606 39:09:47.69N	80:18:47.50W	0
3:36:06 PM	8200 8100T	3606 39:10:11.20N	80:19:09.47W	0
3:36:11 PM	8200 8100T	3606 39:10:18.68N	80:19:06.42W	0
3:36:16 PM	8200 8100T	3606 39:10:28.57N	80:19:11.97W	0
3:36:02 PM	8200 8100T	3606 39:10:00.33N	80:18:48.60W	0
3:36:35 PM	8200 8100T	3606 39:11:03.35N	80:19:35.84W	0
3:36:39 PM	8200 8100T	3606 39:11:13.93N	80:19:50.81W	0
3:36:25 PM	8200 8100T	3606 39:10:46.49N	80:19:25.90W	0
3:36:30 PM	8200 8100T	3606 39:10:54.06N	80:19:34.71W	0
3:36:44 PM	8200 8100T	3606 39:11:24.05N	80:19:53.23W	0
3:35:43 PM	8200 8100T	3606 39:09:19.71N	80:18:19.24W	0
3:35:47 PM	8200 8100T	3606 39:09:31.22N	80:18:30.96W	0
3:35:52 PM	8200 8100T	3606 39:09:39.61N	80:18:33.44W	0
3:34:37 PM	8200 8100T	3606 39:07:15.59N	80:17:06.12W	0
3:34:27 PM	8200 8100T	3606 39:06:56.84N	80:16:42.47W	0
3:34:32 PM	8200 8100T	3606 39:07:09.06N	80:16:47.09W	0
3:34:41 PM	8200 8100T	3606 39:07:22.35N	80:16:58.49W	0
3:34:46 PM	8200 8100T	3606 39:07:30.51N	80:17:03.62W	0
3:34:51 PM	8200 8100T	3606 39:07:43.94N	80:17:14.28W	0
3:34:22 PM	8200 8100T	3606 39:06:48.20N	80:16:32.31W	0
3:32:11 PM	8200 8100T	3606 39:02:42.05N	80:13:44.99W	0
3:31:52 PM	8200 8100T	3606 39:02:04.50N	80:13:24.28W	0
3:31:56 PM	8200 8100T	3606 39:02:12.30N	80:13:24.53W	0
3:32:01 PM	8200 8100T	3606 39:02:23.74N	80:13:22.88W	0
3:32:06 PM	8200 8100T	3606 39:02:30.90N	80:13:25.11W	0

3:32:20 PM	8200 8100T	3606 39:02:57.02N 80:14:00.56W	0
3:32:25 PM	8200 8100T	3606 39:03:08.47N 80:14:10.04W	0
3:32:30 PM	8200 8100T	3606 39:03:15.69N 80:14:11.82W	0
3:32:44 PM	8200 8100T	3606 39:03:42.31N 80:14:26.08W	0
3:32:49 PM	8200 8100T	3606 39:03:49.46N 80:14:24.02W	0
3:32:53 PM	8200 8100T	3606 39:03:57.50N 80:14:34.62W	0
3:32:34 PM	8200 8100T	3606 39:03:23.51N 80:14:13.56W	0
3:32:39 PM	8200 8100T	3606 39:03:34.36N 80:14:17.07W	0
3:32:16 PM	8200 8100T	3606 39:02:49.24N 80:13:45.07W	0
3:31:38 PM	8200 8100T	3606 39:01:39.17N 80:13:04.78W	0
3:31:42 PM	8200 8100T	3606 39:01:46.03N 80:13:17.53W	0
3:31:47 PM	8200 8100T	3606 39:01:57.58N 80:13:11.81W	0
3:31:33 PM	8200 8100T	3606 39:01:28.43N 80:12:45.31W	0
3:32:58 PM	8200 8100T	3606 39:04:04.79N 80:14:37.92W	0
3:45:09 PM	8200 8100T	3606 39:27:23.58N 80:30:29.03W	0
3:45:14 PM	8200 8100T	3606 39:27:22.69N 80:30:40.81W	0
3:45:18 PM	8200 8100T	3606 39:27:35.24N 80:30:42.43W	0
3:48:03 PM	7700 7600T	3606 39:32:01.30N 80:34:01.45W	0
3:48:08 PM	0 0T	3606 39:32:15.02N 80:33:52.69W	0
3:48:13 PM	5200 5100T	3606 39:32:12.70N 80:33:49.15W	0
3:48:18 PM	3200 3100T	3606 39:32:14.12N 80:33:47.58W	0
3:47:54 PM	7900 7800T	3606 39:32:00.31N 80:33:30.11W	0
3:47:59 PM	8000 7900T	3606 39:31:59.72N 80:33:43.96W	0
3:47:40 PM	8300 8200T	3606 39:31:54.75N 80:33:10.72W	0
3:47:44 PM	8200 8100T	3606 39:32:03.94N 80:33:13.83W	0
3:46:20 PM	8200 8100T	3606 39:29:28.50N 80:31:57.77W	0
3:46:24 PM	8200 8100T	3606 39:29:42.13N 80:31:57.25W	0
3:46:38 PM	8200 8100T	3606 39:30:08.50N 80:32:07.33W	0
3:46:43 PM	8100 8000T	3606 39:30:08.93N 80:32:25.57W	0
3:46:29 PM	8200 8100T	3606 39:29:51.61N 80:31:59.64W	0
3:46:34 PM	8200 8100T	3606 39:30:02.80N 80:32:01.26W	0
3:46:01 PM	8200 8100T	3606 39:28:58.61N 80:31:32.09W	0
3:45:46 PM	8200 8100T	3606 39:28:28.50N 80:31:17.70W	0
3:45:51 PM	8100 8000T	3606 39:28:35.42N 80:31:23.80W	0
3:45:56 PM	8200 8100T	3606 39:28:54.43N 80:31:24.51W	0
3:45:33 PM	8200 8100T	3606 39:28:05.41N 80:30:57.65W	0
3:45:37 PM	8200 8100T	3606 39:28:17.55N 80:31:03.86W	0
3:45:23 PM	13300 13200T	3606 39:27:51.05N 80:30:46.69W	0
3:45:42 PM	8200 8100T	3606 39:28:28.09N 80:31:06.71W	0
3:46:06 PM	8200 8100T	3606 39:29:11.96N 80:31:32.04W	0
3:46:10 PM	8200 8100T	3606 39:29:13.69N 80:31:41.95W	0
3:46:15 PM	8200 8100T	3606 39:29:29.69N 80:31:39.21W	0
3:46:53 PM	8200 8100T	3606 39:30:31.30N 80:32:27.68W	0
3:46:58 PM	8200 8100T	3606 39:30:38.78N 80:32:32.90W	0
3:47:02 PM	8200 8100T	3606 39:30:48.57N 80:32:34.69W	0
3:47:07 PM	8200 8100T	3606 39:31:01.45N 80:32:34.19W	0
3:47:16 PM	8200 8100T	3606 39:31:09.61N 80:32:50.65W	0

3:47:21 PM	8200 8100T	3606 39:31:29.94N 80:32:46.99W	0
3:47:12 PM	8200 8100T	3606 39:31:10.01N 80:32:37.13W	0
3:46:48 PM	8200 8100T	3606 39:30:25.54N 80:32:14.72W	0
3:47:35 PM	8300 8200T	3606 39:31:52.80N 80:33:00.59W	0
3:42:52 PM	8100 8000T	3606 39:23:12.94N 80:27:52.20W	0
3:42:57 PM	0 0T	3606 39:23:30.64N 80:27:54.21W	0
3:43:06 PM	8200 8100T	3606 39:23:41.69N 80:28:03.52W	0
3:43:35 PM	8200 8100T	3606 39:24:26.92N 80:28:36.45W	0
3:43:49 PM	8100 8000T	3606 39:24:54.66N 80:28:52.02W	0
3:43:54 PM	8200 8100T	3606 39:25:03.19N 80:28:56.91W	0
3:43:44 PM	8100 8000T	3606 39:24:44.88N 80:28:46.94W	0
3:43:25 PM	8200 8100T	3606 39:24:11.40N 80:28:24.23W	0
3:43:30 PM	8200 8100T	3606 39:24:21.84N 80:28:29.20W	0
3:44:41 PM	8200 8100T	3606 39:26:21.85N 80:29:52.20W	0
3:44:12 PM	8200 8100T	3606 39:25:27.15N 80:29:19.41W	0
3:44:17 PM	8200 8100T	3606 39:25:45.89N 80:29:16.96W	0
3:44:27 PM	8200 8100T	3606 39:25:50.68N 80:29:41.90W	0
3:44:31 PM	8200 8100T	3606 39:26:13.21N 80:29:36.24W	0
3:44:36 PM	8200 8100T	3606 39:26:17.13N 80:29:44.98W	0
3:44:22 PM	8200 8100T	3606 39:25:56.91N 80:29:25.91W	0
3:44:55 PM	8200 8100T	3606 39:26:56.72N 80:30:10.49W	0
3:44:59 PM	8200 8100T	3606 39:27:00.80N 80:30:19.09W	0
3:44:46 PM	8200 8100T	3606 39:26:34.46N 80:29:59.75W	0
3:44:50 PM	8200 8100T	3606 39:26:38.13N 80:30:07.77W	0
3:43:58 PM	8200 8100T	3606 39:25:08.86N 80:29:04.55W	0
3:44:03 PM	0 0T	3606 39:25:16.96N 80:29:04.38W	0
3:44:08 PM	8200 8100T	3606 39:25:26.78N 80:29:08.25W	0
3:42:38 PM	8200 8100T	3606 39:22:50.94N 80:27:36.82W	0
3:42:43 PM	8100 8000T	3606 39:22:54.07N 80:27:40.34W	0
3:42:48 PM	8100 8000T	3606 39:23:04.52N 80:27:46.27W	0
3:42:29 PM	8200 8100T	3606 39:22:32.55N 80:27:19.35W	0
3:42:33 PM	8200 8100T	3606 39:22:40.53N 80:27:25.78W	0
3:42:24 PM	8200 8100T	3606 39:22:32.99N 80:27:08.59W	0
