

Rayner Brian

From: Binder, Michael [REDACTED]
Sent: Monday, March 5, 2018 2:15 PM
To: Rayner Brian
Subject: S269C-1 Throttle Rigging Discussion

Per discussion this morning, there are 3 points that I have found where a throttle rig check is required per AMM.

1. After installation of a new engine (Section 3-15, page 3-26)
2. After installation of a new throttle control cable (Section 4-19, page 4-19)
3. After installation of a new carburetor (Section 5-55, page 5-21)

I hope this helps. Please feel free to contact me if you need anything else.

Michael Binder
Safety Systems Manager
[REDACTED] Sikorsky