

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
DATE				
3-4-09	45.3	2.6	47.9	Flight test (Test Pilot [REDACTED])
3-6-09	47.9	1.9	49.8	Flight test
3-11-09	49.8	.2	50.0	Changed oil (synthetic 10w30) + 12 oz Prolong
3-14-09	50.0	1.1	51.1	Flight test
3-30-09	51.1	1.7	52.8	Try Champion Plugs (Bad)
4-4-09	52.8	2.9	55.7	Changed back to NGK
4-5-09	55.7	.7	56.4	Flight test Plugs
9 JULY 2017	220.1			New part (#1) Fuel pump
				2 fuel filters replaced
				adjusted idle jets + float level
				cleaned inside of carb
				[REDACTED] - owner
26 AUG	232.9			Secured wires on bottom of carb with RTV. CHANGED PLUGS (NGK BKR5E-11) and put standoffs on plug wires.
				[REDACTED] cert # [REDACTED]