



MEMORANDUM for RECORD

Ralph E. Hicks
Senior Air Safety Investigator
Eastern Region Aviation

Date: February 1, 2018
Request sent to: Mr. Walter Jones – Pilot and Owner of N8560P
NTSB Accident Number: ERA17LA006 – Scottsboro, AL

- On January 15, 2018, this investigator emailed Mr. Jones a request for maintenance information related to N8560P.
- As of February 1, 2018, no reply from Mr. Jones has been received.
- Mr. Jones did not submit a NTSB Form 6120.1 (Pilot/Operator Aircraft Accident Report) following the accident.

Hicks Ralph

From: Hicks Ralph
Sent: Monday, January 15, 2018 11:33 AM
To: walter.jones [REDACTED]
Cc: Hicks Ralph
Subject: NTSB Case # ERA17LA006 - N8560P, PA-24, near Scottsboro AL (10/6/2016)

Good morning Walter,

I am following up on the accident involving N8560P from 10/6/2016. Joel Clark from the Birmingham FAA FSDO provided me with most of the information, including your written statement and flight times. I am still missing some maintenance history on the airplane.

If you still have the logbooks, I would appreciate emailed photographs (or text me photos at [REDACTED]) of the last annual inspection on the airframe and engine. If you no longer have the logbooks, please provide the following information (a best estimate will suffice).

Date of last annual inspection prior to the accident
Aircraft total time at last inspection prior to the accident
Engine total time and time since major overhaul as of last annual inspection.

Thanks for your assistance. Please give me a call if you have any questions.

Ralph E. Hicks
Senior Air Safety Investigator – NTSB
Eastern Region Aviation
[REDACTED]
Ashburn, Virginia 20147
[REDACTED]