



Photo 1 – Intermittent skid marks exiting runway 5. (Photo courtesy of FAA)



Photo 2 – View of the left side of the airplane resting on slope. (Photo courtesy of FAA)



Photo 3 – The tail and left wing of the airplane visible behind the approach lighting. (Photo courtesy of the FAA)