

TONG AIRCRAFT SERVICES, INC.

Name: FLIGHT CENTER US

Address: FXE

Zip Code

Fax:

Telephone:

Aircraft Mfg. CESSNA 172S

Register No.: N497SJ

Serial No.:172S8397

Date: 10/17/2016

Estimate

NOSE SECTION REPAIR.

1 R&R PROPELLER ,ENGINE.

2 REMOVE AND REPLACE LOWER FIREWALL, FIREWALL REINFORCEMENT.

3 REPLACE LOWER FIREWALL LOWER ANGLE SUPPORT.

4 REPLACE UPPER AND LOWER SUPPORT NOSE GEAR FITTING.

5 REMOVE AND REPLACE L/H,R/H TUNNEL BULKHEAD.

6 REMOVE AND REPLACE LOWER F.W.D FUSELAGE SKIN.

7 REMOVE AND REPLACE L/H,R/H FLOOR BOARD.

8 REPLACE SEVERAL COWLING SHOCK MOUNTS.

9 REPAIR L/H,R/H LOWER ENGINE COWLING SKINS.

10 REPLACE CENTER LOWER COWLING INDUCTION FAIRING.

11 REPLACE NEW SHIMMY DAMPENER.

12 REPLACE NOSE GEAR LOWER SHOCK FORK ASSEMBLY

13 REPLACE NOSE GEAR TUBE SHOCK STRUT.AND CAP ASSY.

14 REPLACE BOTH STEERING RODS AND BOOTS.

16 REMOVE ENGINE MOUNT SEND OUT FOR INSPECTION.& REINSTALL.

19 REPLACE ALL ENGINE SHOCK MOUNTAND HARDWARE.

20 REPLACE ALL NEW HARDWARE .

21 PAINTED REPAIR AREA.AND ISSUE FAA 337 RETURN TO SERVICE.

LABOR 200HRS

AIRFRAME PARTS

ENGINE INSPECTION BY CERTIFIED ENGINE

NEW PROPELLER

TOTAL PARTS AND LABOR.

THIS ESTIMATE IS NOT INCLUDE HIDDING DAMAGE.

Labor

Parts

Sub Total

Deposit

Balance

Tax

N/A

N/A

Sub Total

Tax

Total

N/A