



## MEMORANDUM FOR RECORD

**Heidi Kemner**  
**Air Safety Investigator**  
**Eastern Region Aviation**

**January 12, 2017**

---

**Subject:** ERA17LA037  
**Who:** Bryce K. Bock - Mechanic

Mr. Bock helped examine the engine under the federal oversight of Inspector Gonzalez. During the examination, he noted the following:

- After the removal of the carburetor, carburetor heat box, intake pipes, and the exhaust system no debris was found inside the engine that would have damaged the No. 1 spark plugs.