



Photo 1 – View of Airplane as Found (F.I.T.)



Photo 2 – View of Firewall and Fuselage Damage (F.I.T.)



Photo 3 – View of Thermal Damage to Battery Solenoid Cable and Neighboring Wires. (Textron)



Photo 4 – View of Muffler after Recovery. (Textron)