



MEMORANDUM FOR RECORD

Todd Gunther
Air Safety Investigator
Eastern Region

Date: March 16, 2021
Subject: Non-Submittal of NTSB Form 6120
NTSB Accident Number: ERA17LA092

The National Transportation Safety Board investigated the accident involving N979BA, which occurred on 01/21/2017.

Rules pertaining to aircraft accidents contained in Part 830 of the Safety Board Regulations require that the pilot or operator submit a completed Pilot/Operator Aircraft Accident Report, NTSB Form 6120 within ten days of the accident.

As of the date of this Memorandum, the Safety Board has not received the required form despite multiple requests to the pilot's legal counsel.