

YEAR:	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspection
DATE				Entries must be endorsed with Name of Technician or Repair Facility. (See back pages)
7/12/2016			Airframe	SN# 310R0717
Aircraft Total Time: 7714.2 Hobbs; 2977.7				
Annual Inspection performed at this time. Aircraft lubed and serviced IAW Cessna 310R Service Manual. Performed gear retraction and emergency extension found satisfactory. ELT battery due August 2017 functional check IAW FAR 91.207(d) found satisfactory. Installed new bracket air filters PN# BA-17. Installed new vacuum relief filters PN# B3-5-1. Checked all fuel screens. Installed right hand aft nacelle tank in wing locker in accordance with STC2504CE and drawings supplied by manufacturer. See form 337 and also weight and balance change. I certify that this AIRCRAFT has been inspected in accordance with an ANNUAL inspection and was determined to be in an airworthy condition.				
Jerry D Spurlock A&P [REDACTED]				
7/16			HOBBS 3026.2	INSTALLED NEW GOODYEAR RECAP 650X10 8ply TIRE. [REDACTED] A&P [REDACTED]

Photo 1 – Airframe Logbook Annual Inspection July 12, 2016

YEAR:	RECORDING	TODAYS	TOTAL	Description of Inspection, Tests, Repairs and Alterations
7/7/2015	Maint hbs	2946.7	Total time 7683.2	Heater 1499
At this time performed ANNUAL INSPECTION. Removed inspection plates, inspected, lubed controls, installed plates. Service brake reservoir, brakes, wheels, tires, and landing gear.				
Checked ELT IAW 91.207. ELT battery is due Aug 2017 Installed new BP-1020 ELT battery.				
Inspected air filters. Dressed propellers. Cleaned and lubed yoke shafts				
Repaired fiberglass wear on cowlings bowls and repainted. Resealed nose gear shimmy dampner.				
Repaired intake ducting for airconditioner.				
Performed retraction test.				
CW AD 95-24-05 by inspection for red oil leakage. No leakage noted.				
Recurring AD's are as follows:				
95-24-05	Propeller hub cracks		ea Pre flt	Due Next preflt
		And	ea Ann	Due Next Ann
			ea 250 hrs leak ck	Due 1741.3 Htr Hobbs
81-09-09	Stewart Warner heaters		Time left	242.3
			ea 1000 hrs overhaul	Due 1994.6 Htr Hobbs
			Time left	495.6
AD's researched thru 7/7/2015 I CERTIFY THIS AIRCRAFT HAS BEEN INSPECTED IN				
ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN				
AIRWORTHY CONDITION AT THIS TIME.				
NAME	[Redacted Signature] A&P [Redacted]			
	Willis Clay Derryberry			

Photo 2 – Airframe Logbook Annual Inspection July 7, 2015