


SERVICE BULLETIN COMPLIANCE RECORD

DATE OF COMPLIANCE	TOTAL TIME IN	TYPE C'D (X)	NEXT COMPLIANCE	AUTHORIZED SIGNATURE	REMARKS
	infinity Flight Group, LLC • Trenton Mercer Airport • 10 West Piper Ave, Trenton, NJ 08628 Phone (609) 853-0800 • Fax (609) 853-0855				
	 INFINITY Since Last Inspection: 82.4	REG #	N378ES	DATE:	09-09-2016
MAKE:		Lycoming	W/O #:	1609001	
MODEL:		IO-540-AB1A5	TACH:	2200.0	
S/N:		L-25913-43A	TSMOH:	859.5	
	- C/W Annual Inspection and servicing IAW Cessna Inspection Guide 182S MM Chap. 5-10-01, REV. 1. and requirements of 14 C.F.R. 43 Appendix D. Compressions checked @ 80 PSI #1) 78 #2) 74 #3) 77 #4) 77 #5) 76 #6) 79. - Drained oil. Inspected filter and screen. Installed new AA48110-2 oil filter and 9 Qts. Aeroshell 15W50 oil. Cleaned, Gapped, Tested and Rotated Spark Plugs IAW Lycoming SI. 1042AA. Installed 1 new Champion REM. Installed 1 new Champion REM8E Spark Plug. - Checked ADs through Bi-weekly 2016-18. - Complied with the following: 13-11-11 Engine Oil Pressure Switch Replacement Due: 5117.6 Tach. 15-19-07 Fuel Injector Lines by visual inspection; next due at Tach 2300.0, 09-2017, or any maintenance to lines. - Slick 500-hour Magneto Service IAW L-1363F Manual. Installed new M3081 Contact Assemblies both mags. Timed mags to factory spec. - Ground run, operational and leak checks satisfactory.				
I certify that this Engine has been inspected IAW Cessna 182S Annual Inspection and 14 C.F.R 43 Appendix D requirements, and was determined to be in airworthy condition. Pertinent details of the inspection are on file at this agency under the work number shown above.					
 [REDACTED] for Infinity Flight Group, LLC Matthew L. Miller A [REDACTED] IA					