



Figure 1 Airplane after being removed from the runway and the gear extended (Photo courtesy of the FAA)



Figure 2 Substantial damage to the ribs and stringers (Photo courtesy of the FAA)