

MEMORANDUM OF RECORD

Eric Alleyne
Air Safety Investigator
National Transportation Safety Board
Office of Aviation Safety - Eastern
Region

NTSB Case Number: ERA17LA204

Subject: NTSB Material Laboratory
Visual examination of right landing gear
trunnion

After a visual inspection of the landing gear trunnion nothing was noted that suggested a preexisting cracking in the fracture. The landing gear piece that fits inside pried the part and overstressed it