

DATE N747CB
19__ S/N 754

Tach: 253.6 AFTT: 3311.2
25 Jan 2007

ONS
ABER
ENTRS

Remove nose gear upper drag strut, check actuator rod for cracks. Rig nose gear. Check shimmy dampener collar for cracks, none found. Re-torque wing attach bolts as needed. Remove & replace sheared rivets in top IB LH wing in spar cap. Tighten rivets in top IB RH wing spar cap. Replace broken RH main gear switch wires at gear down circuit, ops check light function, good. Replace rudder boot. Replace rear rudder push tube with serviceable tube. Remove corrosion, mounting area, whip antenna LH wing. Replace taxi lamp. Install red lens in cockpit overhead light. Route RH bilge pump wiring to hot relay. Service RH oleo. Replace nose gear actuator o'rings. Replace nose tire. Replace compass card. Replace o'rings in pilot RH master cylinder. Replace shaft o'rings in flap selector valve. Tighten fuel boost pump fittings. Replace dorsal fin rivets as needed. Rig LH rudder, LH & RH elevator trim, LH & RH aileron to travel specs. Repair minor crack RH aft side of cowl. Re-safety air box attach bolts. Replace air filter element. Service LH main gear oleo. Replace RH wheel bearings. Replace RH nose wheel bearing & race. Fill wheels with grease. Replace RH gear down hydraulic hose. Replace lower cavity bent line. ELT battery expired. **New ELT expire June 2008.** Replace RH cowl door bottom hinge, 3 segments of top hinge. Tighten hull bellcrank pivots as needed. Install alternator cooling hose. Replace horizontal stab seal. Free-up rudder push rod bearing. Replace floor tinnermans as needed. Treat aircraft with Corrosion-X corrosion inhibitor as practical. Comply with Lake Service Bulletin **B-76** Trunion Tube Inspection & Treatment; by inspecting & treating trunion tubes & gear legs with LPS3; **due next 100 hr./ annual insp.** Comply with **AD2005-12-2** Horizontal Stab Fittings; by installing Lake Central Air Services horizontal stab fittings P/N LC-2200-21, S/N 667 & 668, on LH & RH side, per 337 this date & AMOC letter dated Sept. 19, 2005 for continued airworthiness & removal of 850 life limit on part; **visual compliance only**

NS
BER OF
TRIES.)

ATC TRANSPONDER TEST

The transponder tests and inspection required by FAR 91.413 were performed this date and found to comply with FAR 43, Appendix F.

ACTIONS, TESTS, REPAIRS AND ALTERATIONS
WITH NAME, RATING AND CERTIFICATE NUMBER OF
Y. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)

Make: NARCO Model: ATSOA S/N 4267Z

Date: 01-26-07 Inspected by [REDACTED]

Custom Avionics

418 Bartow Municipal Airport

Bartow, FL 33830

Repair Station # [REDACTED]

N747CB

N747CB
S/N 754

Tach/AFTT: 3335.77
7 June 2007

Remove gear selector valve, install check valve, reinstall with new fittings. Ops check, good.

Amphibians Plus 863-534-8025

R.B. Mount A&P [REDACTED]

up all
SB,
and
implied
436 R1.
2007.

R293X

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
19__				

N747CB
S/N 754

Tach/AFTT: 3465.94
16 July 2009

Troubleshoot hydraulic system for leak, found leak in flap actuator. Remove actuator, replace o'rings, service & reinstall. Ops check, good.

Amphibians Plus 863-534-8025

Samuel C. Seymour A&P

5/14/2011 N747CB TT: 3525 hrs
Serviced hydraulic system with Mil-spec 5606
And replaced high pressure check valve PN:
10116-65 (deltrol) cmm # 10B1 . checked
to see if system pressure held---no defects noted.
Jerry Fuhrman A&P

DATE	RECORD TAC TIM
19__	

DATE
19

N747CB
S/N 754

Tach: 253.6 AFTT: 3311.2
25 Jan 2007

NS
BER OF
TRIES.)

A
The transponder to
performed this dat

required by installation of these parts. Visual inspection compliance with this AD next
due Tach 303.6 AFTT 3361.2.

[REDACTED]
Harry Shannon A&P [REDACTED]

DATE: 25 Jan 2007 TACH: 253.6 AFTT: 3311.2 ELT Battery Expire: June 2008
I certify that this AIRFRAME has been inspected in accordance with an ANNUAL Inspection
and was determined to be in an AIRWORTHY condition.

[REDACTED]
Harry Shannon A&P [REDACTED]

Make: NARCO

Date: 01-26-0

N747CB

N747CB
S/N 754

Remove gear's

Amphibians Plt

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
19__				

N747CB
S/N 754

Tach/AFTT: 3465.94
16 July 2009

.Troubleshoot hydraulic system for leak, found leak in flap actuator. Remove actuator, replace o'rings, service & reinstall. Ops check, good.

Amphibians Plus 863-534-8025

Samuel C. Seymour

5/14/2011 N747CB TT: 3525 hrs
Serviced hydraulic system with Mil-spec 5606
And replaced high pressure check valve PN:
10116-65 (deltrol) cmm # 10B1 . checked
to see if system pressure held---no defects noted.
Jerry Fuhrman A&P

DATE	RECORDING TACH TIME
19__	

DATE N747CB
19 S/N 754

Tach: 253.6 AFTT: 3311.2
25 Jan 2007

NS
BER OF
TRIES.)

The transponder
performed this

required by installation of these parts. Visual inspection compliance with this AD next
due Tach 303.6 AFTT 3361.2.

[Redacted Signature]

Harry Shannon A&P [Redacted]

DATE: 25 Jan 2007 TACH: 253.6 AFTT: 3311.2 ELT Battery Expire: June 2008

I certify that this AIRFRAME has been inspected in accordance with an ANNUAL inspection
and was determined to be in an AIRWORTHY condition.

[Redacted Signature]

Harry Shannon A&P [Redacted]

Make: NARC

Date: 01-26

N747CB

N747CB
S/N 754

Remove ge

Amphibians

