



MEMORANDUM FOR RECORD

Investigator: Brian C. Rayner
Senior Air Safety Investigator
Eastern Region

Date: July 2, 2019
Subject: NTSB Form 6120.1
NTSB Accident Number: ERA17LA326 Union City, TN

Narrative:

The owner/operator did not submit an NTSB Form 6120.1.

The pilot provided statements, but shortly after the accident the operator went out of business, and the maintenance records for the airplane were not reviewed.