



MEMORANDUM FOR RECORD

Brian C. Rayner
Senior Air Safety Investigator
Eastern Region Aviation

August 20, 2018

Subject: ERA17LA336 Winder, Georgia
Name: Peter K. Wacker – Pilot/Owner – NTSB Form 6120.1

Mr. Wacker was the pilot of the airplane in the accident referenced above. He did not submit an NTSB Form 6120.1. The information was gathered through the FAA, aircraft records, telephone interview, and other means.

After his interview with an NTSB investigator, a copy of the interview summary was emailed to him for concurrence or comment. Mr. Wacker did not reply.