

Performance Air Inc.



Pickens Airport (KLQK)

09/22/16	SMOH 52.4
A/CT T 52.4	PTT 52.4
Hobbs: 52.4	N484HC Revmaster 2100, sn# 2787

Cleaned and inspected and serviced engine this date I.A.W Revmaster Aviation Service Manual
compressions are as follows: #1 (79), #2 (80), 3 (78), #4 (80).

**I certify that this Engine has been inspected in accordance
with the scope and details of "appendix D" of FAR 43 and was
determined to be in a condition for safe operations.**

IA/AP

9/22/16 TH