



MEMORANDUM for RECORD

Millicent Hill
Air Safety Investigator
Eastern Region Aviation

Date: December 8, 2017
Person Contacted: Eric West

This investigator interviewed Mr. West by telephone. He had listened to the air traffic control (ATC) audio of N9855B, and he stated the following:

- Time of occurrence was 0055Z.
- 1st attempt resulted in a rejected take-off due to a door issue.
- After the 2nd attempt, pilot request he return to the airport due to, "THE ENGINES ARE NOT RUNNING RIGHT."
- He then asked the controller for VECTORS to the field.
- Controller told him he was South of the airport
- "Do you see me?" Asked the pilot.
- "Yes, fly North. Do you see the runway?"
- The pilot asked in the lights were on full.
- The controller responded that they were.
- There were no further communications from the pilot.