

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
2015				
10/12	548.0			I certify that this sailplane has been inspected in accordance with FAR 43, Appendix D AND IS FOUND IN CONDITION FOR SAFE OPERATION. [REDACTED]
10/15/16	655.0			I certify that this sailplane has been inspected in accordance with FAR 43, Appendix D AND IS FOUND IN CONDITION FOR SAFE OPERATION [REDACTED]

DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
2016				
10/20/16	655			Revised VHF Radio 6w 2960 AIR + Boom mike. Installed Becker ARV201 VHF + New Paiker TM 170 Boom mike. [REDACTED]
11/20/16	697			I certify that this sailplane has been inspected in accordance with FAR 43, Appendix D. AND IS FOUND IN CONDITION FOR SAFE OPERATION [REDACTED]
2-12-18				Revised rear wire to fit air into low tire pressure, 22 psi. Not an easy job. Have made notes in the "Spare Parts Catalog" book by A-2 to clarify procedure. [REDACTED]