

YEAR 20 <u>17</u> DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
Sept 29, 2017	3411.78		503.38	SMOH 3411.78 TIT
				ANNUAL INSP per FAR 43. CHK all systems operational A/c spk insp. Install Scott tail wheel Rebuild kit ABI-RBK-32. per Scott 3200 Instructions Replaced tail wheel tire Aero Classic 280:250-4 Tire & tube. Replaced tube in left main tire Aero Classic 6:50-6 service tire air. Chk fluids Chk brakes. Lube Controls & trim VFR SAT CHK C/W. CHK AD's per T-DATA None due. A/c RTN for SVR.
				I CERTIFY THAT <u>this Aircraft</u> HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.
				<u>Sept 29 2017</u> DATE

Photo 1 – Airframe logbook/annual insp.

Photo 2 – Engine logbook/annual insp.

Photo 2 – Engine logbook/annual insp.

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
Sept 29	3411.78	TACH # T/T	503.38 SMOH	
2017	Annual Insp per FAR 43	CHK ADS	T-DATA None	
due	RTAF	SVC		
			I CERTIFY THAT THIS <u>propeller</u> BEING	
			INSPECTED IN ACCORDANCE WITH AN ANNUAL	
			INSPECTION AND WAS DETERMINED TO BE IN	
			AIRWORTHY CONDITION.	
			[Redacted Signature] Sept 29 2017 DATE	
			LYNN W. FORD [Redacted]	

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins

Photo 3 – Propeller logbook/annual