

60111



The Standard

AIRCRAFT LOG

ASA-SA-1

Aircraft Record General Information

Manufacturer Cessna Model 150 J

Serial 15070076 Registration Number N60111

Date of Manufacture _____

Engine(s) currently installed:

Manufacturer Lycoming Model O-360-A4A Serial L-12564-36A

Manufacturer _____ Model _____ Serial _____

Propeller(s) currently installed:

Manufacturer _____ Model _____

Hub Model _____ Serial _____ Serial _____

Blade Model _____ Serial _____ Serial _____ Serial _____

Blade Model _____ Serial _____ Serial _____ Serial _____

N60111 6-19-17 Tach 783.5 ACCT 11,868.78

Installed new ELT batteries and tested ELT battery IAW 91.207—ops check good, battery now due 6-30-2018.
Installed the following new parts: battery p/n G-25 s/n G02952492, rh and lh window latch assembly p/n's CAM1707 & CAM1708, elevator trim rod bushing p/n NAS74A3-004 (1ea), wing fuel drains p/n CAV-170 (2ea), belly fuel drains p/n CAV-160. Installed serviceable fuel caps (2ea), serviceable JPI p/n EGT701-4C, s/n 26133. Cleaned, repacked main wheel bearings. Complied with the following ADs: 2010-09 Seat Track Inspection, 76-07-12 Bendix Ignition Switch test, and 80-11-04 Vertical Nut Plate—no defects noted. I certify this aircraft has been inspected IAW ANNUAL Inspection as per FAR 43 APP D and Cessna Inspection Checklist and was determined to be in airworthy condition and is returned to service.

Andy Rosman

Barrier Island Aviation,

PROPELLER MAINTENANCE RECORD

Position: _____

PITCH RANGE

Propeller Model: 1A170/EFA7556

High/Feather: _____

Propeller S/N: P80630

Start Lock: _____

Blade Design: _____

Low: _____

Blade S/N's: _____

Reverse: _____

No. 1 _____

No. 2 _____

Aircraft Manufacturer Cessna

No. 3 _____

Aircraft Model 150J

No. 4 _____

S/N: 15070076

No. 5 _____

Registration: N60111

No. 6 _____

Sinner Assembly Part No. _____

N60111 5-20-13 Tach 516.7 Actt 11601.7 Tso 1008.81

I certify this propeller has been inspected IAW ANNUAL inspection and was determined to be in airworthy condition and is returned to service

Andy Rosmar

Barrier Island

service

N60111 8-12-13 Tach 615.4 ACCT 11700.68 TSO 1107.51

I certify this propeller has been inspected IAW ANNUAL inspection and was determined to be in airworthy condition and is returned to service

Andy Rosmar

Barrier Island Aviation, Ltd.

N60111 7-16-14 Tach 711.5 Actt 11796.78 Tso 1203.61

I certify this propeller has been inspected IAW 100hr inspection and was determined to be in airworthy condition and is returned to service

Andy Rosmar

Barrier Island Aviation, Ltd.

N60111 6-19-17 Tach 783.5 ACCT 11868.78 TSO 1275.61

I certify this propeller has been inspected IAW ANNUAL inspection and was determined to be in airworthy condition and is returned to service

Andy Rosmar

Barrier Island Aviation, Ltd.

60111

ZOFZ



ASA-SE-1

TEXTRON Lycoming

652 Oliver Street
Williamsport, PA 17701 U.S.A.

CRANKSHAFT S/N
V537915619

TLRED-489
(Rev. 10-96)

This engine has been overhauled/rebuilt in accordance with the applicable Textron Lycoming manuals. All applicable Federal Aviation Administration Airworthiness Directives and Textron Lycoming Service Bulletins have been complied with. All parts have been inspected and have been determined airworthy to return to service. All accessories as part of the type certificate are either new or newly overhauled. Refer to enclosed Form ET001 for applicable accessory part numbers and serial numbers.

Engine Model: O-360-A4A
Serial #: RL-28063-36A
Total Time: 0.0
Work Order #: PL0609003
Date Completed: 6/23/00

Authorized Signature: [Redacted]
Textron Lycoming
652 Oliver Street
Williamsport, PA 17701
Repair Station: EJ1R115K

 Barrier Island Aviation, Ltd.

N60111 8-22-14 Tach 772.7 Acct 11857.98 TSO-1064.07

Removed #2 cylinder because of stuck valve and replaced with serviceable cylinder from Aerodyne Inc W/Q 20585. Drained Oil removed filter, added 8 qts Aeroshell 100 mineral oil and installed a new CH48110-1 oil filter. Installed exhaust gasket (4ea) p/n 77611. Ground run and leak check good.

Andy Rosman

Barrier Island

N60111 6-19-17 Tach 783.5 ACCT 11868.78 TSO 1074.87

Removed all cylinders and replaced with serviceable cylinders p/n LW12427 (4ea). Installed the following new parts: alternator belt p/n 9335, spark plugs p/n REM40E (8ea), oil filter p/n CH48110-1 & serviced with 8qts of Aeroshell Mineral oil, #2 cylinder EGT probe p/n M-111. Checked mag timing. I certify this engine has been inspected IAW ANNUAL Inspection as per 43 APP D and Cessna Inspection Checklist and was determined to be in airworthy condition and is returned to service.

Andy Rosman

Barrier Island Aviation, Ltd.