

DATE	TOTAL TIME IN SERVICE	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
			TOTAL brought forward from previous page
MAKE: Lancair MODEL: LC41 550FG S/N: 41594 REG. NO: 2536T WORK ORDER: 11090		Lincoln Park Aviation Repair Station No. LKPR101K Phone: [REDACTED]	L DATE: 12/4/2015 A/C TSN: 1141.1 HOBBS: 1141.1
Airframe Entries			
(2) REMOVED AND REPLACED CONNECTOR FOR TACH SENSOR WITH NEW CONNECTOR AND PINS.			
The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Pertinent details of the repair are on file at this repair station under work order listed below.			
DATE: 12/4/2015	SIGNED: [REDACTED]	Inspector #2 CR3# LKPR101K	Work Order: 11090 Printed by EBis 3 (datcomedia.com)
MAKE: Lancair MODEL: LC41 550FG S/N: 41594 REG. NO: 2536T WORK ORDER: 11785		Lincoln Park Aviation Repair Station No. LKPR101K Phone: [REDACTED]	2 DATE: 12/14/2017 A/C TSN: 1339.6 TACH: 1339.6
Airframe Entries			
(1) 100HR/ANNUAL/AIRFRAME - JACKED AIRCRAFT, REMOVED WHEELS, GREASED BEARINGS AND GEAR. CHECKED BRAKES, CHECKED RETRACTION AND EMERGENCY EXTENSION (IF EQUIPPED). CHECKED ELECTRICAL SYSTEM AND BATTERY. CHECKED ALL CONTROLS AND LUBED AS NEEDED. REMOVED ALL INSPECTION PLATES. CHECKED STRUCTURE AND LUBRICATED AS REQUIRED. CHECKED COCKPIT BELTS, LIGHTS AND INSTRUMENT OPERATION. INSPECT ELT IN ACCORDANCE WITH FAR 91.207 PARAGRAPHS (C) AND (D). AIRCRAFT CHECKED FOR CONFORMITY TO THE APPROPRIATE TCD'S... (4) RESEARCHED AND UPDATED COMPILED AD & SB LIST.... (5) COMPLIED WITH AD 2007-07-06 R1, BY INSPECTING LINEAR BEARINGS I/A/W SB 007-002E.... (7) REMOVED AND REPLACED EIGHT BRAKE LININGS WITH NEW, P/N: 066-0622. REPLACED CALIPER O-RINGS WITH NEW, P/N: MS28775-222.... (8) REMOVE NOSE WHEEL PAINT, REPAINT, REINSTALL. INSTALL NEW PAINT PROTECTION FILM.... (9) REMOVED AND REPLACED FORWARD ELEVATOR ROD END WITH NEW, P/N: XMR-TM-4. VERIFIED ELEVATOR TRAVELS.... (13) REMOVED AND REPLACED RIGHT STROBE FLASHER BULB WITH NEW, P/N: 02-0250276-00.			
The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Pertinent details of the repair are on file at this repair station under work order listed below.			
DATE: 12/14/2017	SIGNED: [REDACTED]	CR3# LKPR101K	Work Order: 11785 Printed by EBis 3 (datcomedia.com)

SUB-TOTAL this page

TOTAL—Carry forward to next page