

Date	Total Time		Time Since Last Overhaul		Engine Service and Maintenance Record Installations, Inspections, Airworthiness Directives, Special Inspections, Modifications and Service Bulletins
	Hrs.	Min.	Hrs.	Min.	

Brought

ENGINE MODEL:
TSIO-550C
ENGINE S/N: 41594
REG. NO: 2536T
WORK ORDER: 11785



Lincoln Park Aviation

Repair Station No. LKPR101K

Lincoln Park, NJ 07035
Phone: [REDACTED]

DATE: 12/14/2017
A/C TSN: 1339.6
ENG TT: 1339.6
TSMOH:
TACH: 1339.6

Engine Entries

(2) 100HR/ANNUAL/ENGINE - DRAINED OIL, CHANGE FILTER AND/OR CLEANED SCREENS, NO CONTAMINATION FOUND. CLEANED AND GAPPED SPARK PLUGS, CHECK COMPRESSION USING 80 PSI AS REFERENCE: #1 75/80 #2 78/80 #3 75/80 #4 62/80 #5 62/80 #6 62/80. CHECKED FUEL SYSTEM, DRAINED SUMPS. CHECKED MAGS AND TIMING. CHECKED PROP FOR LEAKS AND GREASED IF REQUIRED.... (6) REMOVED #1 & #2 CYLINDERS ASSY. REPLACED WITH TWO REPAIRED CYLINDERS BY PENN YAN AERO WO # 42027 & 42026.... (10) REMOVED AND REPLACED ALL VALVE COVER GASKETS WITH NEW.... (11) ULTRA SONICALLY CLEANED FUEL INJECTORS, REINSTALLED WITH NEW COPPER GASKETS AND O-RINGS.... (12) INSTALL NEW BUSHING FOR EXHAUST CROSSOVER BOLT, P/N: 654309.

The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Pertinent details of the repair are on file at this repair station under work order listed below.

DATE: 12/14/2017

SIGNED: [REDACTED]

Frank R Galella
Certified Repair Station No. LKPR101K

Work Order: 11785

Printed by EBis 3 (datcomedia.com)

ENGINE MODEL:
TSIO-550C
ENGINE S/N: 41594
REG. NO: 2536T
WORK ORDER: 11884



Lincoln Park Aviation

Repair Station No. LKPR101K

Lincoln Park, NJ 07035
Phone: [REDACTED]

DATE: 4/23/2018
A/C TSN: 1362.5
ENG TT: 1362.5
TSMOH:
TACH: 1362.5

Engine Entries

(1) COMPLETED OIL AND FILTER CHANGE, INSPECTED OIL FILTER AND FOUND NO CONTAMINATION. ADDED 8 QTS OF 20W50 OIL.... (2) REMOVE ALL LOWER SPARK PLUGS, TAKE COMPRESSIONS ON ALL SIX CYLINDERS. CLEAN AND TEST 6 LOWER PLUGS AND REINSTALL. #1 70/80 #2 68/80 #3 68/80 #4 55/80 #5 58/80 #6 55/80.

The Aircraft, Airframe, Aircraft Engine, Propeller or Appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is Approved for return to service. Pertinent details of the repair are on file at this repair station under work order listed below.

DATE: 4/23/2018

SIGNED: [REDACTED]

Frank R Galella
Certified Repair Station No. LKPR101K

Work Order: 11884

Printed by EBis 3 (datcomedia.com)

Engine Logbook Entry		Paragon Aircraft Service, Inc.					Authorized Cessna Service Center	
		Fairfield, NJ 07004						
		Phone: [REDACTED]						
Date	N' Number	Make/Model	Serial#	Hobbs	TSMO	Total Time	W. O.	
8/16/2018	N2536T	TSIO-550-C(9)	914393	1395.4			9537	
Changed oil and filter, took Blackstone oil sample. Cut open filter no metal found. Serviced with 7 quarts Phillips 20W50 oil. Run and leak check satisfactory.								
I certify that the work described above was performed in accordance with approved/acceptable data and is approved for return to service with regard to work performed.								
Authorized Signature: [REDACTED]			John L. Longaker A&P [REDACTED]					

[illegible]