

Hicks Ralph

From: Kawamoto Gerald
Sent: Wednesday, October 2, 2019 11:10 AM
To: Hicks Ralph
Cc: Babcock Christopher
Subject: ERA18FA244 (Woburn, Massachusetts) Garmin G1000 SD Card Email Report
Attachments: DSCN9769.jpg; DSCN9770.jpg

Email Report Instructions:

The narrative and attachments from this email report may be used in other reports at the discretion of the IIC. This email, including attachments (if applicable), should also be placed in the docket by the IIC.

Email Report:

The Vehicle Recover Division received an SD card from a Garmin G1000. The device arrived exhibiting no major signs of damage (DSCN9769.jpg, DSCN9770.jpg), however, it was unreadable with laboratory tools. The device was sent to an external data recovery facility for evaluation and it was determined that the device had suffered internal mechanical damage that prevented any data from being recovered.

Prepared by:

Gerald Kawamoto, Recorder Specialist NTSB RE-40