


1969 Piper N8758N

November 18, 2017: Approximately 11:00 AM

I made a takeoff on run way 20 from Bladenboro Airport (3W6) made a circle around the air field, was on final for run way 2 at approximately 200 feet AGL and decided to do a go around and land on run way 20. As I was flying on downwind leg parallel to run way the plane lost power, I tried to establish a glide to make it back to run way 20, plane was rapidly losing altitude and I could not make it to airfield and had to put down in small clearing.

Robert E Hester, Jr

A black rectangular redaction box covering a handwritten signature. The signature appears to be "Robert E Hester, Jr" in cursive script.